



U.S. Department
of Transportation
**Federal Aviation
Administration**

Aviation Safety

New York International Field Office
159-30 Rockaway Boulevard
1 Aviation Plaza, Room 504
Jamaica, NY 11434-4809

June 12, 2024

Mr. Rainer Becker
Accountable Manager
MTU Maintenance Serbia d.o.o
1 Cetvrta Centralna Radna Street
22330, Nova Pazova
Serbia

Dear Mr. Becker:

The New York International Field Office approves Training Program Manual MM02S-08, Revision 08, dated May 31, 2024, for certificate MTUY154E per §145.51(a) (7) and 14 CFR §145.63 effective June 12, 2024

Please contact this office if you have any questions.

Sincerely,

AGAPIOS
HATZIPAVLOU

Digitally signed by
AGAPIOS HATZIPAVLOU
Date: 2024.06.12
09:51:39 -04'00'

Agapios Hatzipavlou
Principal Maintenance Inspector

Repair Station
MTU Maintenance Serbia d.o.o
Četvrta Centralna Radna Street 1
22330 Nova Pazova, Serbia
FAA Cert. No. MTUY154E

Capability List


FAA Repair Station
Certificate No: MTUY154E

Capability List Document Identifier.: CL-MTUBEG-FAA

Revision No: 14

Date: 06/11/2024

Approved by: Airworthiness Regulatory Compliance Specialist, Srdjan Pavlovic


Title, Name & Surname, Signature

Date: 06/11/2024

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
1	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A6549	CASE,ASSY,STG.9,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
2	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1433	CASE,ASSY,STG.9,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
3	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3653	RING,STG.9-R/PATH,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
4	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4163	RING,STG.9-R/PATH,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
5	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A6550	CASE,ASSY,STG.10,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
6	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1434	CASE,ASSY,STG.10,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
7	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3654	RING STG.10-R/PATH,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
8	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4164	RING STG.10-R/PATH,HPC	72-41-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
9	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A6551	CASE ASSY,STG.11,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
10	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7531	CASE,ASSY,STG.11,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
11	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1435	CASE,ASSY,STG.11,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
12	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3655	RING,STG.11-R/PATH,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
13	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4297	RING,STG.11-R/PATH,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
14	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A6552	CASE, ASSY, STG.12,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
15	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1436	CASE, ASSY, STG.12,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
16	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3656	RING,STG.12-R/PATH,HPC	72-41-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
17	14/Nov/22	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4166	RING,STG.12-R/PATH,HPC	72-41-21	Overhaul, Repair, Inspection, Testing
18	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1221	BLADE,STG.2,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
19	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1222	BLADE,STG.2,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
20	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1223	BLADE,STG.2,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
21	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1224	BLADE,STG.2,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
22	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1231	BLADE,STG.3,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
23	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1232	BLADE,STG.3,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
24	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1233	BLADE,STG.3,LPC	72-21-07	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
25	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1234	BLADE,STG.3,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
26	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1241	BLADE,STG.4,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
27	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1242	BLADE,STG.4,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
28	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1243	BLADE,STG.4,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
29	14/Nov/22	Limited Engine	GE - EM PN GEK112081	CF34-10	45P1244	BLADE,STG.4,LPC	72-21-07	Overhaul, Repair, Inspection, Testing
30	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	01R30B4285-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
31	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B2855-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
32	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B2856-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
33	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B3865-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
34	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B4285-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
35	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B4934-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
36	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B5117-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
37	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B6948-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
38	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3170-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
39	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4901-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
40	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4977-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
41	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B5173-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
42	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B6135-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
43	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30P1711-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
44	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30P2401-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
45	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30P2661-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
46	14/Nov/22	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30P2929-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
47	14/Nov/22	Limited Accessories	IAE - CMM PN 2A4412	V2500	3A2337	SUPPORT-ASSY,NO.1	75-24-49	Overhaul, Repair, Inspection, Testing
48	14/Nov/22	Limited Accessories	IAE - CMM PN 2A4412	V2500	3A2350	SUPPORT-ASSY,NO.2	75-24-49	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
49	14/Nov/22	Limited Accessories	IAE - CMM PN 2A4412	V2500	3A2355	SUPPORT-ASSY,NO.3	75-24-49	Overhaul, Repair, Inspection, Testing
50	14/Nov/22	Limited Accessories	IAE - CMM PN 2A4412	V2500	3A2358	SUPPORT-ASSY,NO.4	75-24-49	Overhaul, Repair, Inspection, Testing
51	14/Nov/22	Limited Accessories	IAE - CMM PN 2A4412	V2500	3A2362	SUPPORT-ASSY,NO.5	75-24-49	Overhaul, Repair, Inspection, Testing
52	14/Nov/22	Limited Accessories	IAE - CMM PN 2A4412	V2500	3A2365	SUPPORT-ASSY,NO.6	75-24-49	Overhaul, Repair, Inspection, Testing
53	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	335-191-202-0	LPC BLADE STG. 2	72-21-02	Overhaul, Repair, Inspection, Testing
54	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	335-191-203-0	LPC BLADE STG. 2	72-21-02	Overhaul, Repair, Inspection, Testing
55	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	335-191-204-0	LPC BLADE STG. 2	72-21-02	Overhaul, Repair, Inspection, Testing
56	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	335-191-205-0	LPC BLADE STG. 2	72-21-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
57	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	335-191-302-0	LPC BLADE STG. 3	72-21-02	Overhaul, Repair, Inspection, Testing
58	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	335-191-303-0	LPC BLADE STG. 3	72-21-02	Overhaul, Repair, Inspection, Testing
59	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	335-191-304-0	LPC BLADE STG. 3	72-21-02	Overhaul, Repair, Inspection, Testing
60	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	335-191-305-0	LPC BLADE STG. 3	72-21-02	Overhaul, Repair, Inspection, Testing
61	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-201-0	LPC BLADE STG. 2	72-21-02	Overhaul, Repair, Inspection, Testing
62	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-202-0	LPC BLADE STG. 2	72-21-02	Overhaul, Repair, Inspection, Testing
63	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-203-0	LPC BLADE STG. 2	72-21-02	Overhaul, Repair, Inspection, Testing
64	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-204-0	LPC BLADE STG. 2	72-21-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
65	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-301-0	LPC BLADE STG. 3	72-21-02	Overhaul, Repair, Inspection, Testing
66	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-302-0	LPC BLADE STG. 3	72-21-02	Overhaul, Repair, Inspection, Testing
67	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-303-0	LPC BLADE STG. 3	72-21-02	Overhaul, Repair, Inspection, Testing
68	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-304-0	LPC BLADE STG. 3	72-21-02	Overhaul, Repair, Inspection, Testing
69	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-401-0	LPC BLADE STG. 4	72-21-02	Overhaul, Repair, Inspection, Testing
70	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-402-0	LPC BLADE STG. 4	72-21-02	Overhaul, Repair, Inspection, Testing
71	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-403-0	LPC BLADE STG. 4	72-21-02	Overhaul, Repair, Inspection, Testing
72	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-404-0	LPC BLADE STG. 4	72-21-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
73	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-409-0	LPC BLADE STG. 4	72-21-02	Overhaul, Repair, Inspection, Testing
74	23/Feb/23	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-057-410-0	LPC BLADE STG. 4	72-21-02	Overhaul, Repair, Inspection, Testing
75	23/Feb/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30P2021-01	FAN BLADE	72-31-21	Overhaul, Repair, Inspection, Testing
76	23/Feb/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5A0865	BLADE, A/O STAGE 2.3 LPC	72-32-82	Overhaul, Repair, Inspection, Testing
77	23/Feb/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5A1445	BLADE, A/O STG.1.5 LPC	72-32-82	Overhaul, Repair, Inspection, Testing
78	23/Feb/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5R0091	BLADE, A/O STAGE 2.0 LPC	72-32-82	Overhaul, Repair, Inspection, Testing
79	23/Feb/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5R0180	BLADE, A/O STAGE 2.5 LPC	72-32-82	Overhaul, Repair, Inspection, Testing
80	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3471	HPC STAGE 5 HALF SHROUD ASSY	72-41-33	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
81	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7563	HPC STAGE 5 HALF SHROUD ASSY	72-41-33	Overhaul, Repair, Inspection, Testing
82	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1158	HPC STAGE 5 HALF SHROUD ASSY	72-41-33	Overhaul, Repair, Inspection, Testing
83	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3467	HPC STAGE 3 HALF SHROUD ASSY	72-41-33	Overhaul, Repair, Inspection, Testing
84	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7719	HPC STAGE 3 HALF SHROUD ASSY	72-41-33	Overhaul, Repair, Inspection, Testing
85	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1156	HPC STAGE 3 HALF SHROUD ASSY	72-41-33	Overhaul, Repair, Inspection, Testing
86	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A1093	HPC STAGE 3 HALF SEAL RING	72-41-33	Overhaul, Repair, Inspection, Testing
87	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3025	HPC STAGE 5 ROTOR PATH SEGMENT	72-41-31	Overhaul, Repair, Inspection, Testing
88	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3976	HPC STAGE 5 ROTOR PATH SEGMENT	72-41-31	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
89	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4349	HPC STAGE 5 ROTOR PATH SEGMENT	72-41-31	Overhaul, Repair, Inspection, Testing
90	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7471	HPC STAGE 5 ROTOR PATH SEGMENT	72-41-31	Overhaul, Repair, Inspection, Testing
91	5/Apr/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7573	HPC STAGE 5 ROTOR PATH SEGMENT	72-41-31	Overhaul, Repair, Inspection, Testing
92	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9805	LPC BLADE STAGE 5	72-31-16	Overhaul, Repair, Inspection, Testing
93	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9905	LPC BLADE STAGE 5	72-31-16	Overhaul, Repair, Inspection, Testing
94	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B3705	LPC BLADE STAGE 5	72-31-16	Overhaul, Repair, Inspection, Testing
95	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B4405	LPC BLADE STAGE 5	72-31-16	Overhaul, Repair, Inspection, Testing
96	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9804	LPC BLADE STAGE 4	72-31-15	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
97	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9904	LPC BLADE STAGE 4	72-31-15	Overhaul, Repair, Inspection, Testing
98	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B3404	LPC BLADE STAGE 4	72-31-15	Overhaul, Repair, Inspection, Testing
99	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B3704	LPC BLADE STAGE 4	72-31-15	Overhaul, Repair, Inspection, Testing
100	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9802	LPC BLADE STAGE 2	72-31-13	Overhaul, Repair, Inspection, Testing
101	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9902	LPC BLADE STAGE 2	72-31-13	Overhaul, Repair, Inspection, Testing
102	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B4102	LPC BLADE STAGE 2	72-31-13	Overhaul, Repair, Inspection, Testing
103	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6702	LPC BLADE STAGE 2	72-31-13	Overhaul, Repair, Inspection, Testing
104	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9803	LPC BLADE STAGE 3	72-31-14	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
105	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9903	LPC BLADE STAGE 3	72-31-14	Overhaul, Repair, Inspection, Testing
106	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B3703	LPC BLADE STAGE 3	72-31-14	Overhaul, Repair, Inspection, Testing
107	25/Apr/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B4103	LPC BLADE STAGE 3	72-31-14	Overhaul, Repair, Inspection, Testing
108	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M30P01	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
109	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M30P02	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
110	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M30P03	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
111	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M30P04	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
112	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M36P01	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
113	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M36P02	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing
114	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M36P03	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing
115	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M36P04	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing
116	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M37P01	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
117	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M37P02	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
118	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M37P03	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
119	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M37P04	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
120	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M37P05	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
121	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M37P06	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
122	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M38P01	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
123	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M38P02	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
124	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M38P03	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
125	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M38P04	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
126	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M38P05	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
127	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M38P06	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
128	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M72P01	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
129	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M72P02	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
130	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M72P03	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
131	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M72P04	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
132	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M73P01	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing
133	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M73P02	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing
134	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M73P03	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing
135	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M73P04	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing
136	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M74P01	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
137	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M74P02	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
138	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M74P03	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
139	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M74P04	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
140	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M75P01	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
141	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M75P02	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
142	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M75P03	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
143	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M75P04	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
144	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M92P01	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
145	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M92P01W	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
146	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M92P02	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
147	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M92P03	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
148	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M92P04	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
149	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M92P05	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
150	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M93P01	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing
151	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M93P02	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing
152	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M93P03	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
153	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M93P04	LPC BLADE STAGE 3	72-21-02	Overhaul, Repair, Inspection, Testing
154	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M94P01	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
155	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M94P02	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
156	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M94P03	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
157	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M94P04	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
158	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M95P01	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
159	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M95P01W	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
160	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M95P02	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
161	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M95P03	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
162	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M95P04	LPC BLADE STAGE 5	72-21-02	Overhaul, Repair, Inspection, Testing
163	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1704M43P05	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
164	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1704M43P06	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
165	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1704M43P07	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
166	25/Apr/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1704M43P08	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
167	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3044315-01	COVER, OIL PRESS ADJ..VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
168	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3045286-01	ADAPTER, FUEL HEATER	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
169	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3053049-01	COVER, ALTERNATOR PAD	72-09-94	Overhaul, Repair, Inspection, Testing
170	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3073197-01	ADAPTER , FUEL HEATER	72-09-94	Overhaul, Repair, Inspection, Testing
171	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3078358-01	COVER, COLD START VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
172	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3109908-01	ADAPTER, CHIP DETECTOR	72-09-94	Overhaul, Repair, Inspection, Testing
173	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3113645-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
174	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3113645-02	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
175	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3113724-01	COVER, OIL FILTER	72-09-94	Overhaul, Repair, Inspection, Testing
176	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3114458-01	COVER, SHUT OFF VALVE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
177	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3114872-01	COVER, INPUT SHAFT	72-09-94	Overhaul, Repair, Inspection, Testing
178	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3114956-01	COVER, HEATER	72-09-94	Overhaul, Repair, Inspection, Testing
179	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3115784-01	HOUSING, COLD START VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
180	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3116006-01	COVER, OIL PRESS ADJ..VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
181	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3116456-01	COVER, SHUT OFF VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
182	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3116516-01	COVER, PLAIN, 2-HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
183	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3116517-01	COVER, PLAIN, 2-HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
184	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3120876-01	COVER, COLD START VALVE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
185	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3121535-01	COVER, OIL PRESS REG VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
186	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	ST3387-01	COVER, SHIPP. STARTER GENERA.	72-09-94	Overhaul, Repair, Inspection, Testing
187	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	ST3389-01	COVER, ACC DRIVE	72-09-94	Overhaul, Repair, Inspection, Testing
188	25/Apr/23	Limited Engine	PWC - CIR MANUAL PN 304877	PW200	3116000-01	ELBOW, BREATHER TUBE	72-09-10	Overhaul, Repair, Inspection, Testing
189	26/Apr/23	Limited Engine	GE - EM PN GEK 112031	CF34-8E	4114T15P02	FAN BLADE	72-21-13	Overhaul, Repair, Inspection, Testing
190	26/Apr/23	Limited Engine	GE - EM PN GEK 112031	CF34-8E	4114T31G01	FAN BLADE	72-21-13	Overhaul, Repair, Inspection, Testing
191	26/Apr/23	Limited Engine	GE - EM PN GEK112081	CF34-10	2225M27P02	FAN BLADE	72-21-04	Overhaul, Repair, Inspection, Testing
192	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B4270-01	CONE COMPRESSOR INLET	72-31-40	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
193	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B5082-01	CONE COMPRESSOR INLET	72-31-40	Overhaul, Repair, Inspection, Testing
194	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B5745-01	CONE COMPRESSOR INLET	72-31-40	Overhaul, Repair, Inspection, Testing
195	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1340-01	NUT BEARING RETAINING	72-09-98	Overhaul, Repair, Inspection, Testing
196	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2023-01	NUT TIE ROD RETAINING	72-09-98	Overhaul, Repair, Inspection, Testing
197	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3068-01	NUT RETAINING FAN HUB	72-09-98	Overhaul, Repair, Inspection, Testing
198	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4015-01	NUT TIE ROD RETAINING	72-09-98	Overhaul, Repair, Inspection, Testing
199	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4016-01	NUT	72-09-98	Overhaul, Repair, Inspection, Testing
200	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B3331-01	ADAPTER ASSY, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
201	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B3364-01	PLUG, AGB	72-09-94	Overhaul, Repair, Inspection, Testing
202	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B4804-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
203	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B4929-01	ADAPTER ASSY,AGB,BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
204	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B5110-01	ADAPTER,TUBE,BREATH ER	72-09-94	Overhaul, Repair, Inspection, Testing
205	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B6833-01	ADAPTER,TUBE,BREATH ER	72-09-94	Overhaul, Repair, Inspection, Testing
206	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B6839-01	ADAPTER ASSY, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
207	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B6842-01	CONNECTOR ASSY,AGB,BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
208	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B7349-01	ADAPTER ASSEMBLY, STRAINER	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
209	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B7434-01	ADAPTER, STRAINER, ASSY	72-09-94	Overhaul, Repair, Inspection, Testing
210	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B7456-01	ADAPTER ASSEMBLY, STRAINER	72-09-94	Overhaul, Repair, Inspection, Testing
211	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C1245-01	ADAPTER, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
212	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C1485-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
213	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C1622-01	PLUG PLAIN	72-09-94	Overhaul, Repair, Inspection, Testing
214	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C2808-01	ADAPTER OIL SCAV.	72-09-94	Overhaul, Repair, Inspection, Testing
215	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C2867-01	COVER PLAIN	72-09-94	Overhaul, Repair, Inspection, Testing
216	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C3620-01	COVER, AGB, LOWER	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
217	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C3818-01	ADAPTER, RESTRICTOR,	72-09-94	Overhaul, Repair, Inspection, Testing
218	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C4266-01	ADAPTER ASSY, HYDR.	72-09-94	Overhaul, Repair, Inspection, Testing
219	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C4271-01	TUBE, VENT, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing
220	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C5035-01	ADAPTER ASSY, HYDR.	72-09-94	Overhaul, Repair, Inspection, Testing
221	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C5300-01	ADAPTER, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
222	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30P1367-01	TUBE, SCAVENGE, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing
223	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30P1460-01	COVER ASSY, P2.8/P3 AIR	72-09-94	Overhaul, Repair, Inspection, Testing
224	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30P2701-01	ADAPTER, AC GENERATOR	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
225	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1120-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
226	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1202-01	PLUG, RELIEF VALVE, BALL	72-09-94	Overhaul, Repair, Inspection, Testing
227	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1391-01	PLUG, PLAIN	72-09-94	Overhaul, Repair, Inspection, Testing
228	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1394-01	COVER, PACKING, 2-HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
229	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1741-01	COVER, PACKING, 2-HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
230	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1743-01	COVER, PACKING, TWO HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
231	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1748-01	ELBOW, TUBE TO BOSS	72-09-94	Overhaul, Repair, Inspection, Testing
232	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1771-01	ADAPTER, STRAIGHT, 2 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
233	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2541-01	ADAPTER, FUEL FILTER DRAIN	72-09-94	Overhaul, Repair, Inspection, Testing
234	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2542-01	ADAPTER, FUEL TEMP. SENSOR	72-09-94	Overhaul, Repair, Inspection, Testing
235	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2543-01	ADAPTER, AIR BLEED	72-09-94	Overhaul, Repair, Inspection, Testing
236	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2560-01	ADAPTER ASSY, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
237	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3599-01	COVER, PLAIN, 4-HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
238	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3616-01	PLATE, BLANKING	72-09-94	Overhaul, Repair, Inspection, Testing
239	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3617-01	PLATE, BLANKING	72-09-94	Overhaul, Repair, Inspection, Testing
240	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3751-01	COVER, PLAIN, 4-HOLE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
241	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4127-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
242	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4129-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
243	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4161-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
244	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4271-01	ADAPTER ASSY, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
245	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B5141-01	ADAPTER ASSY, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
246	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B5409-01	PLUG, RELIEF VALVE, BALL	72-09-94	Overhaul, Repair, Inspection, Testing
247	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B5537-01	ADAPTER ASSY, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
248	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B6137-01	ADAPTER ASSY, 3 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
249	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B6163-01	ADAPTER ASSY, BLEED VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
250	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	AS3223	COVER-PLATE	72-09-94	Overhaul, Repair, Inspection, Testing
251	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	MS9954-04	PLUG-MACHINE THD	72-09-94	Overhaul, Repair, Inspection, Testing
252	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	ST3388-01	COVER, ENGINE, ACC. DRIVE	72-09-94	Overhaul, Repair, Inspection, Testing
253	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	ST3687-01	COVER, PACKING, ONE GROOVE, TWO HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
254	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	ST3816-01	COVER, PLAIN	72-09-94	Overhaul, Repair, Inspection, Testing
255	5/May/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	ST6151-01	COVER, PLAIN	72-09-94	Overhaul, Repair, Inspection, Testing
256	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1347M56G01	LPC VANE STG 5	72-23-22	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
257	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1347M56G02	LPC VANE STG 5	72-23-22	Overhaul, Repair, Inspection, Testing
258	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M25G09	LPC VANE STG 5	72-23-22	Overhaul, Repair, Inspection, Testing
259	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M25G10	LPC VANE STG 5	72-23-22	Overhaul, Repair, Inspection, Testing
260	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M25G13	LPC VANE STG 5	72-23-22	Overhaul, Repair, Inspection, Testing
261	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M25G14	LPC VANE STG 5	72-23-22	Overhaul, Repair, Inspection, Testing
262	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M22G04	LPC VANE STG 2	72-25-02	Overhaul, Repair, Inspection, Testing
263	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M22G05	LPC VANE STG 2	72-25-02	Overhaul, Repair, Inspection, Testing
264	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M22G08	LPC VANE STG 2	72-25-02	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
265	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M22G09	LPC VANE STG 2	72-25-02	Overhaul, Repair, Inspection, Testing
266	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M23G05	LPC VANE STG 3	72-25-02	Overhaul, Repair, Inspection, Testing
267	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M23G09	LPC VANE STG 3	72-25-02	Overhaul, Repair, Inspection, Testing
268	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M24G04	LPC VANE STG 4	72-25-02	Overhaul, Repair, Inspection, Testing
269	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M24G05	LPC VANE STG 4	72-25-02	Overhaul, Repair, Inspection, Testing
270	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M24G08	LPC VANE STG 4	72-25-02	Overhaul, Repair, Inspection, Testing
271	8/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M24G09	LPC VANE STG 4	72-25-02	Overhaul, Repair, Inspection, Testing
272	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3041944-01	TUBE ASSY, OIL, INLET	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
273	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3042767-01	COVER, AGB, LOWER	72-09-94	Overhaul, Repair, Inspection, Testing
274	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052405-01	ADAPTER, STRAIGHT, 2 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
275	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052445-01	ADAPTER, STRAIGHT, 2 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
276	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052503-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing
277	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052544-01	COVER PLATE, FAIRING, FRONT	72-09-94	Overhaul, Repair, Inspection, Testing
278	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052555-01	COVER, BEARING	72-09-94	Overhaul, Repair, Inspection, Testing
279	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052572-01	COVER, VALVE, COLD START	72-09-94	Overhaul, Repair, Inspection, Testing
280	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052579-01	COVER, PACKING, 3 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
281	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052593-01	COVER, PACKING, 4 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
282	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052594-01	COVER, PACKING, 1GRV, 2HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
283	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052599-01	COVER PLATE, FAIRING, REAR	72-09-94	Overhaul, Repair, Inspection, Testing
284	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052613-01	TUBE, SUPPORT, IGNITER	72-09-94	Overhaul, Repair, Inspection, Testing
285	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052621-01	ADAPTER, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
286	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052623-01	COVER, PLAIN, 4 HOLES	72-09-94	Overhaul, Repair, Inspection, Testing
287	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052625-01	COVER, TUBE, P3 AIR	72-09-94	Overhaul, Repair, Inspection, Testing
288	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3052930-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
289	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3053033-01	PLUG, SHAFT, LC	72-09-94	Overhaul, Repair, Inspection, Testing
290	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3053035-01	COVER, PACKING, 1GRV, 2HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
291	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3053047-01	COVER, PACKING, 1GRV, 2HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
292	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3053272-01	RESTRICTOR, OIL	72-09-94	Overhaul, Repair, Inspection, Testing
293	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3055234-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing
294	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3055235-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing
295	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3055338-01	ADAPTER, TUBE TO BOSS	72-09-94	Overhaul, Repair, Inspection, Testing
296	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3059060-01	ATTENUATOR ASSY	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
297	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3059062-01	ADAPTER, ATTENUATOR	72-09-94	Overhaul, Repair, Inspection, Testing
298	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3059859-01	COVER, SEAL, GEARSHAFT	72-09-94	Overhaul, Repair, Inspection, Testing
299	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3071800-01	ADAPTER, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
300	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	3073762-01	COVER PLATE, FAIRING, FRONT	72-09-94	Overhaul, Repair, Inspection, Testing
301	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J1493-01	COVER PLATE, FAIRING, REAR	72-09-94	Overhaul, Repair, Inspection, Testing
302	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J1602-01	ADAPTER, TUBE TO BOSS	72-09-94	Overhaul, Repair, Inspection, Testing
303	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J1724-01	COVER, AGB, LOWER	72-09-94	Overhaul, Repair, Inspection, Testing
304	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J1734-01	TUBE ASSY, VENT, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
305	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J1747-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing
306	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J1772-01	COVER, PLAIN	72-09-94	Overhaul, Repair, Inspection, Testing
307	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J1807-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing
308	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J1808-01	COVER, AIR, CABIN	72-09-94	Overhaul, Repair, Inspection, Testing
309	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2013-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing
310	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2156-01	COVER, PLAIN, 4 HOLES	72-09-94	Overhaul, Repair, Inspection, Testing
311	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2382-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing
312	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2383-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
313	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2385-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing
314	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2386-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing
315	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2615-01	ATTENUATOR ASSY	72-09-94	Overhaul, Repair, Inspection, Testing
316	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2616-01	ADAPTER, ATTENUATOR	72-09-94	Overhaul, Repair, Inspection, Testing
317	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2785-01	COVER, SEAL, GEARSHAFT	72-09-94	Overhaul, Repair, Inspection, Testing
318	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2858-01	ADAPTER, TRANSFORMER	72-09-94	Overhaul, Repair, Inspection, Testing
319	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J2979-01	ADAPTER, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
320	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3064-01	TUBE ASSY, OIL, INLET	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
321	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3182-01	COVER PLATE, FAIRING, FRONT	72-09-94	Overhaul, Repair, Inspection, Testing
322	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3183-01	COVER PLATE, FAIRING, FRONT	72-09-94	Overhaul, Repair, Inspection, Testing
323	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3520-01	PLUG, INTERMEDIATE CASE HSG	72-09-94	Overhaul, Repair, Inspection, Testing
324	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3556CL	DUMMY TUBE, VENT, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing
325	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3556CL01	TUBE ASSY, VENT, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing
326	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3556CL02	TUBE ASSY, VENT, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing
327	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3556CL03	TUBE ASSY, VENT, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing
328	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3556CL04	TUBE ASSY, VENT, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
329	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3556CL05	TUBE ASSY, VENT, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing
330	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	30J3556CL06	TUBE ASSY, VENT, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing
331	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1225-01	COVER PLATE, FAIRING, FRONT	72-09-94	Overhaul, Repair, Inspection, Testing
332	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1297-01	PLATE, RETAINING, BEARING	72-09-94	Overhaul, Repair, Inspection, Testing
333	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1301-01	COVER, BEARING	72-09-94	Overhaul, Repair, Inspection, Testing
334	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1370-01	PLUG, SHAFT, LC	72-09-94	Overhaul, Repair, Inspection, Testing
335	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1460-01	COVER, VALVE, COLD START	72-09-94	Overhaul, Repair, Inspection, Testing
336	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1477-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
337	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1501-01	COVER, PACKING, 3 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
338	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1669-01	ADAPTER, STRAIGHT, 2 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
339	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1672-01	COVER, O/S CONTR. LINKAGE	72-09-94	Overhaul, Repair, Inspection, Testing
340	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1785-01	COVER, PACKING, 4 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
341	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1790-01	COVER, PACKING, 1GRV, 2HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
342	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1831-01	COVER PLATE, FAIRING, REAR	72-09-94	Overhaul, Repair, Inspection, Testing
343	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J1899-01	ADAPTER, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
344	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2062-01	COVER, AIR, CABIN	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
345	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2147-01	COVER PLATE, FAIRING, FRONT	72-09-94	Overhaul, Repair, Inspection, Testing
346	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2249-01	COVER, PACKING, 1GRV, 2HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
347	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2267-01	TUBE ASSY, VENT, OIL TANK	72-09-94	Overhaul, Repair, Inspection, Testing
348	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2306-01	TUBE, SUPPORT, IGNITER	72-09-94	Overhaul, Repair, Inspection, Testing
349	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2325-01	COVER, PLAIN	72-09-94	Overhaul, Repair, Inspection, Testing
350	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2383-01	ADAPTER, BREATHER	72-09-94	Overhaul, Repair, Inspection, Testing
351	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2403-01	COVER, PLAIN, 4 HOLES	72-09-94	Overhaul, Repair, Inspection, Testing
352	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2455-01	COVER, TUBE, P3 AIR	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
353	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2561-01	TUBE ASSY, OIL, INLET	72-09-94	Overhaul, Repair, Inspection, Testing
354	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2674-01	ADAPTER, STRAIGHT, 2 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
355	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2742-01	COVER, AGB, LOWER	72-09-94	Overhaul, Repair, Inspection, Testing
356	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2817-01	COVER ASSY, TUBE, AIR	72-09-94	Overhaul, Repair, Inspection, Testing
357	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	31J2890-01	BRACKET, ACCELEROMETER	72-09-94	Overhaul, Repair, Inspection, Testing
358	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	ST3342-01	PLUG, MACHINE	72-09-94	Overhaul, Repair, Inspection, Testing
359	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	ST3525-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
360	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	ST3526-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
361	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	ST3552-01	PLUG, BLANKING	72-09-94	Overhaul, Repair, Inspection, Testing
362	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	ST3613-06	ADAPTER, TUBE TO BOSS	72-09-94	Overhaul, Repair, Inspection, Testing
363	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	ST3661-01	COVER, O/S CONTR. LINKAGE	72-09-94	Overhaul, Repair, Inspection, Testing
364	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	ST3890-01	COVER, PLAIN	72-09-94	Overhaul, Repair, Inspection, Testing
365	8/May/23	Limited Engine	PWC - CIR MANUAL PN 30J2306	PW500	ST6401-01	COVER, 1 GROOVE, 2 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
366	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3390	HPC STAGE 11 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
367	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4328	HPC STAGE 11 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
368	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3387	HPC STAGE 8 CASE	72-41-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
369	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4324	HPC STAGE 8 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
370	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3388	HPC STAGE 9 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
371	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4311	HPC STAGE 9 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
372	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4326	HPC STAGE 9 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
373	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A6511	HPC STAGE 9 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
374	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3389	HPC STAGE 10 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
375	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4526	HPC STAGE 10 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
376	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A5436	HPC STAGE 10 CASE	72-41-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
377	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A5438	HPC STAGE 10 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
378	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A5624	HPC STAGE 10 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
379	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A5676	HPC STAGE 10 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
380	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A6512	HPC STAGE 10 CASE	72-41-21	Overhaul, Repair, Inspection, Testing
381	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4348	HPC STAGE 4 ROTOR PATH SEGMENT	72-41-31	Overhaul, Repair, Inspection, Testing
382	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7470	HPC STAGE 4 ROTOR PATH SEGMENT	72-41-31	Overhaul, Repair, Inspection, Testing
383	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A1427	HPC STAGE 4 HALF SEAL RING	72-41-33	Overhaul, Repair, Inspection, Testing
384	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3469	HPC STAGE 4 HALF SHROUD ASSY	72-41-33	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
385	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7561	HPC STAGE 4 HALF SHROUD ASSY	72-41-33	Overhaul, Repair, Inspection, Testing
386	8/May/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1175	HPC STAGE 4 HALF SHROUD ASSY	72-41-33	Overhaul, Repair, Inspection, Testing
387	12/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M93P01W	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
388	13/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1336M94P01W	LPC BLADE STAGE 4	72-21-02	Overhaul, Repair, Inspection, Testing
389	14/May/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1704M43P05W	LPC BLADE STAGE 2	72-21-02	Overhaul, Repair, Inspection, Testing
390	13/Jun/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4723	HPC Stage 6 Rotor Path Segment	72-41-31	Overhaul, Repair, Inspection, Testing
391	13/Jun/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A5994	HPC Stage 6 Rotor Path Segment	72-41-31	Overhaul, Repair, Inspection, Testing
392	13/Jun/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7576	HPC Stage 6 Rotor Path Segment	72-41-31	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
393	13/Jun/23	Limited Engine	IAE - EM PN 2A4407	V2500	5R0479	BRACKET, A/O A3 G/B MOUNT	72-00-60	Overhaul, Repair, Inspection, Testing
394	13/Jun/23	Limited Engine	IAE - EM PN 2A4407	V2500	5R0480	BRACKET, A/O A3 G/B MOUNT	72-00-60	Overhaul, Repair, Inspection, Testing
395	13/Jun/23	Limited Engine	IAE - EM PN 2A4407	V2500	5R0482	BRACKET, A/O ASSY	72-00-60	Overhaul, Repair, Inspection, Testing
396	13/Jun/23	Limited Engine	IAE - EM PN 2A4407	V2500	5R0483	BRACKET, A/O A2 G/B	72-00-60	Overhaul, Repair, Inspection, Testing
397	4/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	4B0031	LINK, A/O GEARBOX REAR	72-00-60	Overhaul, Repair, Inspection, Testing
398	4/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	4B0112	LINK, A/O GEARBOX FRONT	72-00-60	Overhaul, Repair, Inspection, Testing
399	4/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	6A4700	LPC FAN BLADE	72-31-11	Overhaul, Repair, Inspection, Testing
400	4/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	6A6521	LPC FAN BLADE	72-31-11	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
401	4/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	6A7614	LPC FAN BLADE	72-31-11	Overhaul, Repair, Inspection, Testing
402	4/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	6A7654	LPC FAN BLADE	72-31-11	Overhaul, Repair, Inspection, Testing
403	4/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	6A7655	LPC FAN BLADE	72-31-11	Overhaul, Repair, Inspection, Testing
404	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A2510	CONNEX. VIGV ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
405	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A2521	CONNEX. STG3 ASSY,ACT.STBD	72-41-34	Overhaul, Repair, Inspection, Testing
406	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A2523	CONNEX. STG3 ASSY,ACT.PORT	72-41-34	Overhaul, Repair, Inspection, Testing
407	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A2528	CONNEX. STG4 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
408	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A2534	CONNEX. STG5 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
409	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A2703	CONNEC. STG6 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
410	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A2889	BRACKET ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
411	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A2895	BRACKET ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
412	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3535	RING VIGV UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
413	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3537	RING VIGV LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
414	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3539	RING STG3 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
415	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3541	RING STG3 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
416	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3543	RING STG4 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
417	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3545	RING STG4 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
418	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3547	RING STG5 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
419	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3549	RING STG5 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
420	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3551	RING STG6 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
421	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3553	RING STG6 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
422	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3681	BRACKET ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
423	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3753	RING STG3 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
424	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3982	RING STG3 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
425	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3983	RING STG4 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
426	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3984	RING STG5 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
427	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A3987	RING STG3 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
428	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A4333	CONNEC. STG5 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
429	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A4340	CONNEC. STG4 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
430	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7539	CONNEC. STG5 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
431	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7540	CONNEC. STG4 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
432	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7580	RING VIGV UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
433	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7584	RING VIGV LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
434	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7586	CONNEC. VIGV ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
435	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7588	RING STG3 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
436	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7590	RING STG3 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
437	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7593	CONNEC. STG3 ASSY,ACT.STBD	72-41-34	Overhaul, Repair, Inspection, Testing
438	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7594	CONNEC. STG3 ASSY,ACT.PORT	72-41-34	Overhaul, Repair, Inspection, Testing
439	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7596	RING STG4 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
440	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7599	RING STG4 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
441	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7603	CONNEC. STG4 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
442	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7605	RING STG5 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
443	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7607	RING STG5 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
444	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7611	CONNEC. STG5 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
445	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7847	BRIDGE VIGV ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
446	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7849	RING VIGV UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
447	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7851	RING VIGV LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
448	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7853	BRIDGE STG3 ASSY STBD	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
449	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7855	BRIDGE STG3 ASSY,PORT	72-41-34	Overhaul, Repair, Inspection, Testing
450	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7858	BRIDGE STG4 ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
451	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7860	BRIDGE STG5 ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
452	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7861	RING STG3 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
453	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7863	RING STG3 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
454	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7865	RING STG3 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
455	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7866	BRIDGE STG4 ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
456	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7868	RING STG4 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
457	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7869	BRIDGE STG5 ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
458	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7888	RING,ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
459	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7890	RING STG4 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
460	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7893	CONNEC. STG4 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
461	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7894	RING STG5 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
462	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7896	RING STG5 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
463	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7898	CONNEC. STG5 ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
464	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7899	RING VIGV UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
465	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7901	RING VIGV LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
466	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7903	RING STG3 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
467	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A7906	RING STG3 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
468	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8075	RING VIGV UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
469	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8077	RING VIGV LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
470	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8079	BRIDGE STG4 ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
471	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8080	BRIDGE STG5 ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
472	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8086	RING STG5 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
473	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8088	RING STG5 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
474	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8097	RING STG6 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
475	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8098	RING STG6 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
476	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8115	RING STG3 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
477	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8117	RING STG3 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
478	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8119	RING STG3 LOWER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
479	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8121	RING STG4 UPPER ASSY, ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
480	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8123	BRIDGE STG4 ASSY	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
481	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A8124	BRIDGE STG5 ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
482	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A9106	RING ASSY,VIGV-ACT.RING	72-41-34	Overhaul, Repair, Inspection, Testing
483	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A9108	RING ASSY,ACT.VIGV	72-41-34	Overhaul, Repair, Inspection, Testing
484	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A9110	RING ASSY STG3 UP(*)	72-41-34	Overhaul, Repair, Inspection, Testing
485	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A9112	RING ASSY STG3 LOWER	72-41-34	Overhaul, Repair, Inspection, Testing
486	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A9114	RING ASSY STG4 UP(*)	72-41-34	Overhaul, Repair, Inspection, Testing
487	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A9116	RING ASSY,ST.4,ACT.LO	72-41-34	Overhaul, Repair, Inspection, Testing
488	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A9118	RING ASSY STG.5	72-41-34	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
489	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6A9120	RING ASSY,ST.5,ACT.LO	72-41-34	Overhaul, Repair, Inspection, Testing
490	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6B1068	CONN, ASSY, VIGH ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
491	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6B1069	CONN, ASSY, VIGH ACT.	72-41-34	Overhaul, Repair, Inspection, Testing
492	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6B1084	CONNECTOR,ASSY STG 5	72-41-34	Overhaul, Repair, Inspection, Testing
493	4/Jul/23	Limited Engine	IAE - EM PN 2A4427 and PN 2A4416	V2500	6B1085	CONNECTOR,ASSY STG 5	72-41-34	Overhaul, Repair, Inspection, Testing
494	11/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A0084	SUPPORT-ASSY, DIFFUSER, OUTER	72-50-25	Overhaul, Repair, Inspection, Testing
495	11/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A0090	DIFFUSER-ASSY, SEGMENT, OUTER	72-50-25	Overhaul, Repair, Inspection, Testing
496	11/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A0958	DIFFUSER-A/O, SEGMENT, OUTER	72-50-25	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
497	11/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A1791	DIFFUSER-A/O, SEGMENT, OUTER	72-50-25	Overhaul, Repair, Inspection, Testing
498	11/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A1907	SUPPORT-ASSY, DIFFUSER, OUTER	72-50-25	Overhaul, Repair, Inspection, Testing
499	11/Jul/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A2482	DIFFUSER-A/O, SEGMENT, OUTER	72-50-25	Overhaul, Repair, Inspection, Testing
500	9/Aug/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A2930	HSG, ASSY STG 5 CONN	72-41-34	Overhaul, Repair, Inspection, Testing
501	9/Aug/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4335	HSG, ASSY STG 5 CONN	72-41-34	Overhaul, Repair, Inspection, Testing
502	9/Aug/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A6540	CONE, ASSY OF FRONT SUPPORT	72-41-21	Overhaul, Repair, Inspection, Testing
503	9/Aug/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7577	CONE, ASSY OF FRONT SUPPORT	72-41-21	Overhaul, Repair, Inspection, Testing
504	9/Aug/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1430	CONE, ASSY OF FRONT SUPPORT	72-41-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
505	9/Aug/23	Limited Engine	IAE - EM PN 2A4407	V2500	4B0053	CASING, A/O GEARBOX	72-60-21	Overhaul, Repair, Inspection, Testing
506	9/Aug/23	Limited Engine	IAE - EM PN 2A4407	V2500	4B0054	CASING, A/O GEARBOX	72-60-21	Overhaul, Repair, Inspection, Testing
507	9/Aug/23	Limited Engine	IAE - EM PN 2A4407	V2500	4B0055	CASING	72-60-21	Overhaul, Repair, Inspection, Testing
508	9/Aug/23	Limited Engine	IAE - EM PN 2A4407	V2500	4B0057	CASING, ASSY OF GEARBOX	72-60-21	Overhaul, Repair, Inspection, Testing
509	9/Aug/23	Limited Engine	IAE - EM PN 2A4407	V2500	4B0400	CASING, A/O GBX	72-60-21	Overhaul, Repair, Inspection, Testing
510	9/Aug/23	Limited Engine	IAE - EM PN 2A4407	V2500	4B0402	CASING, ASSY OF GEARBOX	72-60-21	Overhaul, Repair, Inspection, Testing
511	9/Aug/23	Limited Engine	IAE - EM PN 2A4407	V2500	4B0423	CASING, ASSY OF GEARBOX	72-60-21	Overhaul, Repair, Inspection, Testing
512	30/Aug/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	2A0250	HPT CASE	72-45-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
513	30/Aug/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	2A1591	HPT CASE	72-45-21	Overhaul, Repair, Inspection, Testing
514	30/Aug/23	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	2A1600	HPT CASE	72-45-21	Overhaul, Repair, Inspection, Testing
515	30/Aug/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1277M30P06	BLADE-STG 1	72-21-01	Overhaul, Repair, Inspection, Testing
516	30/Aug/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1338M51P01	BLADE-STG 1	72-21-01	Overhaul, Repair, Inspection, Testing
517	30/Aug/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1338M51P02	BLADE-STG 1	72-21-01	Overhaul, Repair, Inspection, Testing
518	30/Aug/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1338M51P03	BLADE-STG 1	72-21-01	Overhaul, Repair, Inspection, Testing
519	30/Aug/23	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1338M51P05	BLADE-STG 1	72-21-01	Overhaul, Repair, Inspection, Testing
520	15/Sep/23	Limited Engine	IAE - EM PN 2A4407	V2500	5W2198	LPC MID CASE	72-32-83	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
521	15/Sep/23	Limited Engine	IAE - EM PN 2A4407	V2500	6A6548	CASE, ASSY, STG.8, HPC COMPR.	72-41-21	Overhaul, Repair, Inspection, Testing
522	15/Sep/23	Limited Engine	IAE - EM PN 2A4407	V2500	6A7529	CASE, ASSY, STG.8, HPC COMPR.	72-41-21	Overhaul, Repair, Inspection, Testing
523	15/Sep/23	Limited Engine	IAE - EM PN 2A4407	V2500	6A7578	CASE, ASSY, STG.8, HPC COMPR.	72-41-21	Overhaul, Repair, Inspection, Testing
524	15/Sep/23	Limited Engine	IAE - EM PN 2A4407	V2500	6A7624	CASE, ASSY, STG.8, HPC COMPR.	72-41-21	Overhaul, Repair, Inspection, Testing
525	15/Sep/23	Limited Engine	IAE - EM PN 2A4407	V2500	6B1432	CASE, ASSY, STG.8, HPC COMPR.	72-41-21	Overhaul, Repair, Inspection, Testing
526	3/Nov/23	Limited Engine	GE - EM PN GEK112081	CF34-10	2226M46P01	RETAINER-STG.1 LPT SHROUD	72-57-23	Overhaul, Repair, Inspection, Testing
527	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A0807	CASE-ASSY, LPT	72-50-21	Overhaul, Repair, Inspection, Testing
528	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A0990	CASE-ASSY, LPT	72-50-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
529	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A0991	CASE-ASSY, LPT	72-50-21	Overhaul, Repair, Inspection, Testing
530	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A1908	CASE-ASSY, LPT	72-50-21	Overhaul, Repair, Inspection, Testing
531	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A2183	CASE-ASSY, LPT	72-50-21	Overhaul, Repair, Inspection, Testing
532	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A2265	CASE-ASSY, LPT	72-50-21	Overhaul, Repair, Inspection, Testing
533	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A2447	CASE-ASSY, LPT	72-50-21	Overhaul, Repair, Inspection, Testing
534	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	3A2533	CASE-A/O, LPT	72-50-21	Overhaul, Repair, Inspection, Testing
535	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	5A0433	VANE, A/O STG 2.0 LPC	72-32-83	Overhaul, Repair, Inspection, Testing
536	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	5A0436	VANE, ASSY STG 1.5 LPC	72-32-83	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
537	3/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	5A1412	STATOR, A/O STG 2.3	72-32-83	Overhaul, Repair, Inspection, Testing
538	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B2905-01	COVER, VALVE, COLD START	72-09-94	Overhaul, Repair, Inspection, Testing
539	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B4991-01	COVER,BLEED AIR,REAR	72-09-94	Overhaul, Repair, Inspection, Testing
540	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B5589-01	ADAPTER,ELBO,TUBE TO BOSS	72-09-94	Overhaul, Repair, Inspection, Testing
541	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B5662-01	COVER,AIR BLEED,HIGH PRESS	72-09-94	Overhaul, Repair, Inspection, Testing
542	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B6048-01	ADAPTER, 1 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
543	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1445-01	ADAPTER ASSY, TUBE TO BOSS	72-09-94	Overhaul, Repair, Inspection, Testing
544	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1446-01	ADAPTER, STRAIGHT	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
545	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1485-01	PLUG, MACHINE	72-09-94	Overhaul, Repair, Inspection, Testing
546	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1503-01	ADAPTER, STRAIGHT, 2 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
547	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1698-01	PLUG, BLEEDER, TUBE	72-09-94	Overhaul, Repair, Inspection, Testing
548	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1979-01	ADAPTER, STRAIGHT	72-09-94	Overhaul, Repair, Inspection, Testing
549	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2244-01	COVER, LP BLEED, PAD	72-09-94	Overhaul, Repair, Inspection, Testing
550	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2245-01	RETAINER, TUBE, CABIN AIR	72-09-94	Overhaul, Repair, Inspection, Testing
551	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2683-01	ADAPTER, STRAIGHT, TWO HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
552	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3641-01	COVER, O/S CONTR. LINKAGE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
553	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3689-01	PLUG	72-09-94	Overhaul, Repair, Inspection, Testing
554	3/Nov/23	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4201-01	COVER-BLANKING	72-09-94	Overhaul, Repair, Inspection, Testing
555	13/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	5A1422	BRACKET, A/O T/MOUNT NO. 2	71-21-11	Overhaul, Repair, Inspection, Testing
556	13/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	5A1423	BRACKET, A/O T/MNT NO. 10	71-21-11	Overhaul, Repair, Inspection, Testing
557	13/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	5A1431	BRACKET, A/O T/MOUNT NO. 2	71-21-11	Overhaul, Repair, Inspection, Testing
558	13/Nov/23	Limited Engine	IAE - EM PN 2A4407	V2500	5A1432	BRACKET, A/O T/MOUNT NO. 10	71-21-11	Overhaul, Repair, Inspection, Testing
559	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9392	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing
560	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9882	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
561	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9882-001	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing
562	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B2772	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing
563	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B2772-002	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing
564	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6182	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing
565	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6182-001	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing
566	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6192	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing
567	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6382-01	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing
568	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6382-021	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
569	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6482-01	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing
570	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6482-021	LP COMP.STTR Y STG 2	72-31-26	Overhaul, Repair, Inspection, Testing
571	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7672-001	VANE,LPC,STG2	72-31-26	Overhaul, Repair, Inspection, Testing
572	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7672-01	VANE,LPC,STG2	72-31-26	Overhaul, Repair, Inspection, Testing
573	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7772-001	VANE,LPC,STG2	72-31-26	Overhaul, Repair, Inspection, Testing
574	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7772-01	VANE,LPC,STG2	72-31-26	Overhaul, Repair, Inspection, Testing
575	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9393	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
576	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9473	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
577	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9783	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
578	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9783-001	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
579	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9883	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
580	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9883-001	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
581	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B2473	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
582	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B2473-002	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
583	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B2773	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
584	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B2773-002	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
585	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6183	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
586	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6183-001	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
587	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6193	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
588	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6273	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
589	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6283	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
590	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6283-001	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
591	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6383-01	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
592	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6383-021	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
593	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6483-01	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
594	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6483-021	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
595	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7283-021	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
596	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7293-021	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
597	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7673-001	VANE,LPC,STG3	72-31-27	Overhaul, Repair, Inspection, Testing
598	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7673-01	VANE,LPC,STG3	72-31-27	Overhaul, Repair, Inspection, Testing
599	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7773-001	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing
600	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7773-01	LP COMP.STTR Y STG 3	72-31-27	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
601	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9394	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing
602	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9394-001	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing
603	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9884	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing
604	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1A9884-001	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing
605	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B2774	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing
606	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B2774-002	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing
607	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6184	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing
608	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6184-001	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
609	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B6394-021	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing
610	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7284-021	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing
611	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7674-001	VANE,LPC,STG4	72-31-28	Overhaul, Repair, Inspection, Testing
612	13/Nov/23	Limited Engine	PW - EM PN 1A6231	PW2000	1B7674-01	LP COMP.STTR Y STG 4	72-31-28	Overhaul, Repair, Inspection, Testing
613	12/Jan/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M68G01	CASING-BOOSTER STATOR	72-25-03	Overhaul, Repair, Inspection, Testing
614	12/Jan/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M68G04	FAN STATOR CASE STG 2-4	72-25-03	Overhaul, Repair, Inspection, Testing
615	12/Jan/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M68G04SB 084	FAN CASE STATOR STG 2-4	72-25-03	Overhaul, Repair, Inspection, Testing
616	12/Jan/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M68G05	FAN STATOR CASE STG 2-4	72-25-03	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
617	12/Jan/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M68G05SB 084	FAN STTR CASE STG2-4	72-25-03	Overhaul, Repair, Inspection, Testing
618	12/Jan/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M68G06	BOOSTER CASE STG.2-4	72-25-03	Overhaul, Repair, Inspection, Testing
619	12/Jan/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9385M68G10	BOOSTER CASE STG.2-4	72-25-03	Overhaul, Repair, Inspection, Testing
620	12/Jan/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1070	CONNECTOR,ASSY STG 3	72-41-34	Overhaul, Repair, Inspection, Testing
621	12/Jan/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1071	CONNECTOR,ASSY STG 3	72-41-34	Overhaul, Repair, Inspection, Testing
622	12/Jan/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1081	CONNECTOR,ASSY STG 4	72-41-34	Overhaul, Repair, Inspection, Testing
623	12/Jan/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6B1082	CONNECTOR,ASSY STG 4	72-41-34	Overhaul, Repair, Inspection, Testing
624	12/Jan/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5A1184	HOUSING, A/O CENTRE BRG, PTO	72-32-05	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
625	12/Jan/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5A1433	HOUSING, A/O CENTRE BRG, PTO	72-32-05	Overhaul, Repair, Inspection, Testing
626	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2070M12G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
627	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2070M13G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
628	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2070M14G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
629	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2070M15G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
630	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2070M16G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
631	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M79G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
632	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M80G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
633	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M81G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
634	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M82G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
635	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M83G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
636	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M84G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
637	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M85G01	FLOW SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
638	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M03G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
639	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M04G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
640	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M05G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
641	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M06G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
642	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M07G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
643	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M08G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
644	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M09G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
645	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M10G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
646	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M11G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
647	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M12G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
648	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M13G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
649	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2601M14G01	FLOWPATH SEGMENT	72-23-07	Overhaul, Repair, Inspection, Testing
650	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	45P1041	Splitter	72-23-09	Overhaul, Repair, Inspection, Testing
651	12/Jan/24	Limited Engine	GE - EM PN GEK112031 AND GEK112031-1	CF34-8E	4114T06P01	FAN BLADE RETAINING PIN	72-21-12	Overhaul, Repair, Inspection, Testing
652	12/Jan/24	Limited Engine	GE - EM PN GEK112031 AND GEK112031-1	CF34-8E	4114T06P02	FAN BLADE RETAINING PIN	72-21-12	Overhaul, Repair, Inspection, Testing
653	12/Jan/24	Limited Engine	GE - EM PN GEK112031 AND GEK112031-1	CF34-8E	4114T06P03	FAN BLADE RETAINING PIN	72-21-12	Overhaul, Repair, Inspection, Testing
654	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M87G01	LPT AIR DUCT	72-57-14	Overhaul, Repair, Inspection, Testing
655	12/Jan/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M88G01	LPT TEE AIR DUCT	72-57-14	Overhaul, Repair, Inspection, Testing
656	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30A1307	FLANGE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
657	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30A1321	PLUG-BLANKING	72-09-94	Overhaul, Repair, Inspection, Testing
658	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30A2152	PLUG-A/O,BLANKING	72-09-94	Overhaul, Repair, Inspection, Testing
659	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B3501-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
660	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B3877-01	ADAPTER, FLANGED TEE	72-09-94	Overhaul, Repair, Inspection, Testing
661	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B4030-01	ADAPTER, 1 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
662	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B5055-01	ADAPTER, FLANGED TEE	72-09-94	Overhaul, Repair, Inspection, Testing
663	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B5322-01	ADAPTER, FLANGED TEE	72-09-94	Overhaul, Repair, Inspection, Testing
664	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30B5866-01	ADAPTER, DRAIN VALVE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
665	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C1570-01	COVER, VALVE COLD ST	72-09-94	Overhaul, Repair, Inspection, Testing
666	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C1650-01	TUBE, SUPP., FUEL N	72-09-94	Overhaul, Repair, Inspection, Testing
667	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C1652-01	COVER, TUBE, SUPPORT	72-09-94	Overhaul, Repair, Inspection, Testing
668	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C1919-01	ADAPTER, STRAIGHT	72-09-94	Overhaul, Repair, Inspection, Testing
669	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C1930-01	ADAPTER, STRAIGHT, 2	72-09-94	Overhaul, Repair, Inspection, Testing
670	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C3442-01	PLUG, PO AIR, EEC TO	72-09-94	Overhaul, Repair, Inspection, Testing
671	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C3669-01	TEE, ADAPTER	72-09-94	Overhaul, Repair, Inspection, Testing
672	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C4005-01	COVER ASSY, P2.8 / P	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
673	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C4141-01	PLUG LOW PRESSURE	72-09-94	Overhaul, Repair, Inspection, Testing
674	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C4421-01	TUBE, SUPP., FUEL NO	72-09-94	Overhaul, Repair, Inspection, Testing
675	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C4576-01	COVER ASSY, P2.8 /P3	72-09-94	Overhaul, Repair, Inspection, Testing
676	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C4583-01	PLUG, BLANKING, CONN	72-09-94	Overhaul, Repair, Inspection, Testing
677	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C4719-01	COVER ASSY, P2.8/ P3	72-09-94	Overhaul, Repair, Inspection, Testing
678	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C4721-01	COVER, P2.8/P3 AIR,	72-09-94	Overhaul, Repair, Inspection, Testing
679	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30C4987-01	TEE, ADAPTER	72-09-94	Overhaul, Repair, Inspection, Testing
680	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	30P0318-01	PLUG LP SHAFT	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
681	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1422-01	PLUG, LC SHAFT, REAR COVER, O/S CONTR. LINKAGE	72-09-94	Overhaul, Repair, Inspection, Testing
682	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1486-01	COVER, O/S CONTR. LINKAGE	72-09-94	Overhaul, Repair, Inspection, Testing
683	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B1975-01	ADAPTER, DRAIN VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
684	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2205-01	ADAPTER, STRAIGHT	72-09-94	Overhaul, Repair, Inspection, Testing
685	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2342-01	ADAPTER, TUBE TO BOSS	72-09-94	Overhaul, Repair, Inspection, Testing
686	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2343-01	PLUG, BLANKING	72-09-94	Overhaul, Repair, Inspection, Testing
687	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2344-01	ADAPTER, STRAIGHT	72-09-94	Overhaul, Repair, Inspection, Testing
688	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2353-01	COVER, O/P ADJUSTING VALVE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
689	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2722-01	ADAPTER, FLANGE	72-09-94	Overhaul, Repair, Inspection, Testing
690	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2880-01	ATE, BLANKING, P2.8 BOS	72-09-94	Overhaul, Repair, Inspection, Testing
691	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B2903-01	COVER, BLEED VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
692	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3141-01	ADAPTER, FLANGED TEE	72-09-94	Overhaul, Repair, Inspection, Testing
693	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3230-01	COVER ASSY, BLEED VALV	72-09-94	Overhaul, Repair, Inspection, Testing
694	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3349-01	COVER, PLATE	72-09-94	Overhaul, Repair, Inspection, Testing
695	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3855-01	ACKET, MOUNT, FILLER NE	72-09-94	Overhaul, Repair, Inspection, Testing
696	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3878-01	ATE, BLANKING, P2.8 BOS	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
697	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3977-01	COVER, PLAIN, FLANGED	72-09-94	Overhaul, Repair, Inspection, Testing
698	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B3978-01	PLATE, BLANKING, 2 HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
699	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4404-01	ADAPTER, FLANGED TEE	72-09-94	Overhaul, Repair, Inspection, Testing
700	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4487-01	COVER, PACKING	72-09-94	Overhaul, Repair, Inspection, Testing
701	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4831-01	ADAPTER, STRAIGHT	72-09-94	Overhaul, Repair, Inspection, Testing
702	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4888-01	ADAPTER, TWO HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
703	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B4917-01	ADAPTER, TWO HOLE	72-09-94	Overhaul, Repair, Inspection, Testing
704	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B5326-01	COVER, VALVE, COLD START	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
705	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	31B6278-01	ADAPTER, STRAIGHT	72-09-94	Overhaul, Repair, Inspection, Testing
706	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	MS9902-03	PLUG	72-09-94	Overhaul, Repair, Inspection, Testing
707	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	MS9902-04	PLUG-MACHINE THD	72-09-94	Overhaul, Repair, Inspection, Testing
708	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	ST3317-01	ADAPTER, DRAIN VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
709	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	ST3342-01	PLUG, MACHINE	72-09-94	Overhaul, Repair, Inspection, Testing
710	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	ST3661-01	OVER, O/S CONTR. LINKAGE	72-09-94	Overhaul, Repair, Inspection, Testing
711	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	ST3679-01	PLUG, GEARSHAFT, OIL PUMP	72-09-94	Overhaul, Repair, Inspection, Testing
712	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	ST6111-01	ADAPTER, DRAIN VALVE	72-09-94	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
713	12/Jan/24	Limited Engine	PWC - CIR MANUAL PN 30B4133	PW300	ST6126-01	ADAPTER, DRAIN VALVE	72-09-94	Overhaul, Repair, Inspection, Testing
714	12/Jan/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A2925	HSG, ASSY STG 3 CONN	72-41-34	Overhaul, Repair, Inspection, Testing
715	12/Jan/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3988	HSG, ASSY STG 3 CONN	72-41-34	Overhaul, Repair, Inspection, Testing
716	27/Feb/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A2927	HSG, ASSY STG 4 CONN	72-41-34	Overhaul, Repair, Inspection, Testing
717	27/Feb/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4810	HSG, ASSY STG 4 CONN	72-41-34	Overhaul, Repair, Inspection, Testing
718	27/Feb/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4343	HOUSING, ASSY	72-41-34	Overhaul, Repair, Inspection, Testing
719	27/Feb/24	Limited Engine	GE- EM PN GEK105091 AND GEK9250	CF34-8C	4118T70P01	LINER OUTER-TRANSITION	72-57-03	Overhaul, Repair, Inspection, Testing
720	27/Feb/24	Limited Engine	GE- EM PN GEK105091 AND GEK9250	CF34-8C	4118T70P02	LINER OUTER-TRANSITION	72-57-03	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
721	27/Feb/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5R0029	VANE,LPC,STG2.5	72-32-76	Overhaul, Repair, Inspection, Testing
722	27/Feb/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5R0097	STATOR,A/O STG 2.5 LPC	72-32-76	Overhaul, Repair, Inspection, Testing
723	27/Feb/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5R0168	STATOR,A/O STG 2.5 LPC	72-32-76	Overhaul, Repair, Inspection, Testing
724	27/Feb/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5R0189	STATOR,A/O STG 2.5 LPC	72-32-76	Overhaul, Repair, Inspection, Testing
725	27/Feb/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5R0195	STATOR,A/O STG 2.5 LPC	72-32-76	Overhaul, Repair, Inspection, Testing
726	27/Feb/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5R6088	VANE,LPC,STG2.5	72-32-76	Overhaul, Repair, Inspection, Testing
727	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M72G05	MANIFOLD-AIR	72-57-15	Overhaul, Repair, Inspection, Testing
728	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M72G06	MANIFOLD-AIR	72-57-15	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
729	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M72G07	MANIFOLD-AIR	72-57-15	Overhaul, Repair, Inspection, Testing
730	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M72G08	MANIFOLD-AIR	72-57-15	Overhaul, Repair, Inspection, Testing
731	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2227M63G01	MANIFOLD-AIR	72-57-15	Overhaul, Repair, Inspection, Testing
732	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2227M63G02	MANIFOLD-AIR	72-57-15	Overhaul, Repair, Inspection, Testing
733	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2227M63G03	MANIFOLD-AIR	72-57-15	Overhaul, Repair, Inspection, Testing
734	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2227M63G04	MANIFOLD-AIR	72-57-15	Overhaul, Repair, Inspection, Testing
735	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2070M37G03	FAIRING STRUT	72-23-23	Overhaul, Repair, Inspection, Testing
736	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2070M37G04	FAIRING-STRUT	72-23-23	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
737	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M56P01	FAIRING-STRUT	72-23-23	Overhaul, Repair, Inspection, Testing
738	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M56P02	FAIRING-STRUT	72-23-23	Overhaul, Repair, Inspection, Testing
739	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M93P01	FAIRING-STRUT	72-23-23	Overhaul, Repair, Inspection, Testing
740	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M93P02	FAIRING-STRUT	72-23-23	Overhaul, Repair, Inspection, Testing
741	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2131M65G01	FAIRING-STRUT	72-23-23	Overhaul, Repair, Inspection, Testing
742	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2072M71G01	SUPPORT	72-23-23	Overhaul, Repair, Inspection, Testing
743	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2070M23G01	ACT RING ASSY	72-23-14	Overhaul, Repair, Inspection, Testing
744	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2070M44G01	CASE REAR	72-32-01	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
745	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2131M99G01	SUPPORT	72-23-23	Overhaul, Repair, Inspection, Testing
746	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	9303M42P02	COUPLING	72-09-01	Overhaul, Repair, Inspection, Testing
747	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	AS1895-1-225	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
748	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	AS1895-1-300	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
749	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	AS1895-4-125	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
750	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	AS1895-4-150	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
751	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	AS1895-4-200	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
752	27/Feb/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	AS1895-4-300	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
753	27/Feb/24	Limited Engine	GE - EM PN GEK105091	CF34-8C	9303M42P02	COUPLING	72-09-01	Overhaul, Repair, Inspection, Testing
754	27/Feb/24	Limited Engine	GE - EM PN GEK105091	CF34-8C	AS1895-1-225	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
755	27/Feb/24	Limited Engine	GE - EM PN GEK105091	CF34-8C	AS1895-4-125	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
756	27/Feb/24	Limited Engine	GE - EM PN GEK105091	CF34-8C	AS1895-4-175	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
757	27/Feb/24	Limited Engine	GE - EM PN GEK105091	CF34-8C	AS1895-4-200	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
758	27/Feb/24	Limited Engine	GE - EM PN GEK105091	CF34-8C	AS1895-4-250	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
759	27/Feb/24	Limited Engine	GE - EM PN GEK105091	CF34-8C	AS1895-4-300	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
760	27/Feb/24	Limited Engine	GE- EM-GEK112031	CF34-8E	9303M42P02	COUPLING	72-09-01	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
761	27/Feb/24	Limited Engine	GE- EM-GEK112031	CF34-8E	AS1895-1-225	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
762	27/Feb/24	Limited Engine	GE- EM-GEK112031	CF34-8E	AS1895-1-300	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
763	27/Feb/24	Limited Engine	GE- EM-GEK112031	CF34-8E	AS1895-4-125	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
764	27/Feb/24	Limited Engine	GE- EM-GEK112031	CF34-8E	AS1895-4-200	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
765	27/Feb/24	Limited Engine	GE- EM-GEK112031	CF34-8E	AS1895-4-250	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
766	27/Feb/24	Limited Engine	GE- EM-GEK112031	CF34-8E	AS1895-4-300	COUPLING, V-RETAINER	72-09-01	Overhaul, Repair, Inspection, Testing
767	27/Feb/24	Limited Engine	GE - EM PN GEK105091 AND GEK105091-1	CF34-8C	4114T15P02	FAN BLADE	72-21-13	Overhaul, Repair, Inspection, Testing
768	27/Feb/24	Limited Engine	GE - EM PN GEK105091 AND GEK105091-1	CF34-8C	4114T31G01	FAN BLADE	72-21-13	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
769	27/Feb/24	Limited Engine	GE- EM PN GEK105091 AND GEK105091-1	CF34-8C	4114T06P01	FAN BLADE RETAINING PIN	72-21-12	Overhaul, Repair, Inspection, Testing
770	27/Feb/24	Limited Engine	GE- EM PN GEK105091 AND GEK105091-1	CF34-8C	4114T06P02	FAN BLADE RETAINING PIN	72-21-12	Overhaul, Repair, Inspection, Testing
771	27/Feb/24	Limited Engine	GE- EM PN GEK105091 AND GEK105091-1	CF34-8C	4114T06P03	FAN BLADE RETAINING PIN	72-21-12	Overhaul, Repair, Inspection, Testing
772	27/Feb/24	Limited Engine	GE- EM PN GEK112031 AND GEK9250	CF34-8E	4118T70P01	LINER OUTER- TRANSITION	72-57-03	Overhaul, Repair, Inspection, Testing
773	27/Feb/24	Limited Engine	GE- EM PN GEK112031 AND GEK9250	CF34-8E	4118T70P02	LINER OUTER- TRANSITION	72-57-03	Overhaul, Repair, Inspection, Testing
774	11/Jun/24	Limited Engine	GE- EM PN GEK112031 AND GEK112031-1	CF34-8E	1822M28G03	CASE-COMP	72-32-06	Overhaul, Repair, Inspection, Testing
775	11/Jun/24	Limited Engine	GE- EM PN GEK112031 AND GEK112031-1	CF34-8E	1822M28G04	CASE-COMP	72-32-06	Overhaul, Repair, Inspection, Testing
776	11/Jun/24	Limited Engine	GE- EM PN GEK112031 AND GEK112031-1	CF34-8E	1822M28G05	CASE-COMP	72-32-06	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
777	11/Jun/24	Limited Engine	GE- EM PN GEK112031 AND GEK112031-1	CF34-8E	1822M28P01	COMP C UPP	72-32-06	Overhaul, Repair, Inspection, Testing
778	11/Jun/24	Limited Engine	GE- EM PN GEK112031 AND GEK112031-1	CF34-8E	1822M28P02	COMP LOW	72-32-06	Overhaul, Repair, Inspection, Testing
779	11/Jun/24	Limited Engine	GE- EM PN GEK112031 AND GEK112031-1	CF34-8E	4923T98G03	CASE-COMP	72-32-06	Overhaul, Repair, Inspection, Testing
780	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	5A0211	RETAINER, RING ASSY, BLADE, REAR	72-31-12	Overhaul, Repair, Inspection, Testing
781	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	5A0897	RETAINER, RING ASSY, BLADE, REAR	72-31-12	Overhaul, Repair, Inspection, Testing
782	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	308M32G01	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
783	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G03	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
784	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G04	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
785	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G05	LINK, SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
786	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G06	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
787	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G07	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
788	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G08	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
789	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G11	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
790	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G12	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
791	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G14	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
792	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G17	LINK SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
793	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G19	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
794	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G20	LINK	72-09-04	Overhaul, Repair, Inspection, Testing
795	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G21	LINK	72-09-04	Overhaul, Repair, Inspection, Testing
796	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G22	LINK-SUPPORT, RIGHT SIDE	72-09-04	Overhaul, Repair, Inspection, Testing
797	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G23	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
798	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G24	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
799	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G27	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
800	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1308M32G34	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
801	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1310M25G03	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
802	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1473M58G01	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
803	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1473M58P01	HOUSING, BEARING (SPD)	72-09-04	Overhaul, Repair, Inspection, Testing
804	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1578M30G02	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
805	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1578M30G08	LINK, SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
806	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1578M30G12	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
807	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1578M30G14	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
808	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1578M30G18	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
809	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1578M30G21	LINK SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
810	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1578M30G22	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
811	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1578M30G28	LINK SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
812	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1578M30G36	LINK,SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
813	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1578M30G49	LINK-SUPPORT	72-09-04	Overhaul, Repair, Inspection, Testing
814	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1854M36P01	SPACER-STG 1	72-21-11	Overhaul, Repair, Inspection, Testing
815	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9326M60P01	SPACER,STG 1	72-21-11	Overhaul, Repair, Inspection, Testing
816	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2230M39G01	SHAFT RDS	72-62-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
817	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	5A6024	RACE, ASSY OUTER TUBE MOUNT	71-21-11	Overhaul, Repair, Inspection, Testing
818	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M91P02	BOLT, SLABBED	72-55-06	Overhaul, Repair, Inspection, Testing
819	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M91P03	BOLT, SLABBED	72-55-06	Overhaul, Repair, Inspection, Testing
820	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M92P02	BOLT DOUBLE HEX	72-55-06	Overhaul, Repair, Inspection, Testing
821	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M93P02	BOLT	72-55-06	Overhaul, Repair, Inspection, Testing
822	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2227M70P01	BOLT	72-55-06	Overhaul, Repair, Inspection, Testing
823	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2228M14P01	BOLT, DOUBLE HEX	72-55-06	Overhaul, Repair, Inspection, Testing
824	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2030M21G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
825	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2030M30G01	TUBE-FUEL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
826	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2030M32G01	TUBE-OIL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
827	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2030M35G01	TUBE-OIL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
828	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2030M37G01	TUBE-OIL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
829	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2030M39G01	TUBE-OIL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
830	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2035M75G01	TUBE-OIL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
831	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2053M12P01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing
832	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2053M29G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
833	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2058M87G01	TUBE	72-09-04	Overhaul, Repair, Inspection, Testing
834	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2058M90G01	MANIFOLD-AIR	72-09-04	Overhaul, Repair, Inspection, Testing
835	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2059M27G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing
836	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2098M46P01	TUBE-FUEL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
837	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2098M53G01	MANIFOLD-FUEL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
838	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2170M10G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing
839	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2170M38G01	TUBE-FUEL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
840	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2176M26G01	TUBE-OIL (SCAVENGE)	72-09-04	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
841	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2176M32G01	TUBE-OIL (VENT)	72-09-04	Overhaul, Repair, Inspection, Testing
842	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2177M12G01	MANIFOLD-FUEL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
843	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2177M35G01	MANIFOLD-OIL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
844	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2191M89P01	TUBE-OIL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
845	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2226M77G01	TUBE-A/O OIL DRAIN	72-09-04	Overhaul, Repair, Inspection, Testing
846	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2278M69G01	MANIFOLD-FUEL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
847	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2284M27G01	TUBE-OIL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
848	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2284M48G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
849	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2284M49G01	DUCT-LPTACC	72-09-04	Overhaul, Repair, Inspection, Testing
850	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2284M77G01	MANIFOLD-FUEL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing
851	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2284M80G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing
852	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2284M81G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing
853	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2284M82G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing
854	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2284M83G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing
855	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2290M97G01	TUBE-OIL (SCAVENGE)	72-09-04	Overhaul, Repair, Inspection, Testing
856	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2298M26G01	TUBE-FUEL (DRAIN)	72-09-04	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
857	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2367M92G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing
858	11/Jun/24	Limited Engine	GE - EM PN GEK112081	CF34-10E	2369M19G01	TUBE-AIR	72-09-04	Overhaul, Repair, Inspection, Testing
859	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	5A0460	FAIRING, SPLITTER FRONT	72-32-93	Overhaul, Repair, Inspection, Testing
860	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3651	RING,ST.7-R/PATH	72-41-21	Overhaul, Repair, Inspection, Testing
861	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4101	RING ST.7 PATH HP- COMP	72-41-21	Overhaul, Repair, Inspection, Testing
862	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4161	RING,ST.7-R/PATH	72-41-21	Overhaul, Repair, Inspection, Testing
863	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A5992	RING ST.7 PATH HP- COMP	72-41-21	Overhaul, Repair, Inspection, Testing
864	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A5995	RING ST.7 PATH HP- COMP	72-41-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
865	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7623	RING ST.7 PATH HP-COMP	72-41-21	Overhaul, Repair, Inspection, Testing
866	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7626	RING ST.7 PATH HP-COMP	72-41-21	Overhaul, Repair, Inspection, Testing
867	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A3652	RING, ST.8 R/PATH	72-41-21	Overhaul, Repair, Inspection, Testing
868	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4102	RING ST.8 PATH HP-COMP	72-41-21	Overhaul, Repair, Inspection, Testing
869	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A4162	RING ST.8 PATH HP-COMP	72-41-21	Overhaul, Repair, Inspection, Testing
870	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A5993	RING ST.8 PATH HP-COMP	72-41-21	Overhaul, Repair, Inspection, Testing
871	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A5996	RING ST.8 PATH HP-COMP	72-41-21	Overhaul, Repair, Inspection, Testing
872	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7625	RING ST.8 PATH HP-COMP	72-41-21	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
873	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	6A7627	RING ST.8 PATH HP- COMP	72-41-21	Overhaul, Repair, Inspection, Testing
874	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2082M79G03	VANE-OUTLET GUIDE STG 9	72-41-03	Overhaul, Repair, Inspection, Testing
875	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2082M79G04	VANE-OUTLET GUIDE STG 9	72-41-03	Overhaul, Repair, Inspection, Testing
876	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2082M79G05	VANE-OUTLET GUIDE STG 9	72-41-03	Overhaul, Repair, Inspection, Testing
877	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2082M79G06	VANE-OUTLET GUIDE STG 9	72-41-03	Overhaul, Repair, Inspection, Testing
878	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2082M79G07	VANE-OUTLET GUIDE STG 9	72-41-03	Overhaul, Repair, Inspection, Testing
879	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2082M79G08	VANE-OUTLET GUIDE STG 9	72-41-03	Overhaul, Repair, Inspection, Testing
880	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2082M79G09	VANE-OUTLET GUIDE STG 9	72-41-03	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
881	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2082M79G10	VANE-OUTLET GUIDE STG 9	72-41-03	Overhaul, Repair, Inspection, Testing
882	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2459M04G01	VANE-OUTLET GUIDE STG 9	72-41-03	Overhaul, Repair, Inspection, Testing
883	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	4B7049	.CASING,A/O,AIR PORT	72-60-31	Overhaul, Repair, Inspection, Testing
884	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	4B7153	CASING,A/O DEOILER	72-60-31	Overhaul, Repair, Inspection, Testing
885	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	4B7262	CASING, A/O DEOILER	72-60-31	Overhaul, Repair, Inspection, Testing
886	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	4B7361	CASING DEOILER	72-60-31	Overhaul, Repair, Inspection, Testing
887	11/Jun/24	Limited Engine	IAE - EM PN 2A4416	V2500	4B7049	CASING,A/O,AIR PORT	72-60-31	Overhaul, Repair, Inspection, Testing
888	11/Jun/24	Limited Engine	IAE - EM PN 2A4416	V2500	4B7291	CASING, A/O DEOILER	72-60-31	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
889	11/Jun/24	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-252-305-0	SHIM-FAN BLADE	72-21-22	Overhaul, Repair, Inspection, Testing
890	11/Jun/24	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-252-306-0	SHIM-FAN BLADE	72-21-22	Overhaul, Repair, Inspection, Testing
891	11/Jun/24	Limited Engine	CFMI-TP-SM 10	CFM56-7	340-252-307-0	SHIM-FAN BLADE	72-21-22	Overhaul, Repair, Inspection, Testing
892	11/Jun/24	Limited Engine	GE- EM-GEK112031	CF34-8E	4138T62G04	ENG AFT MT	71-20-01	Overhaul, Repair, Inspection, Testing
893	11/Jun/24	Limited Engine	PW - EM PN5319156 and PN585005	PW1100G	30G2976-01	CASE HPT	72-51-11	Overhaul, Repair, Inspection, Testing
894	11/Jun/24	Limited Engine	PW - EM PN5319156 and PN585005	PW1100G	30G4127-01	CASE HPT, ASSY	72-51-11	Overhaul, Repair, Inspection, Testing
895	11/Jun/24	Limited Engine	PW - EM PN5319156 and PN585005	PW1100G	30G4184-01	CASE HPT, ASSY	72-51-11	Overhaul, Repair, Inspection, Testing
896	11/Jun/24	Limited Engine	PW - EM PN5319156 and PN585005	PW1100G	30G4185-01	CASE HPT, ASSY	72-51-11	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
897	11/Jun/24	Limited Engine	GE- EM PN GEK112031	CF34-8E	3066T16G04	CASE-FAN BLD	72-23-01	Overhaul, Repair, Inspection, Testing
898	11/Jun/24	Limited Engine	GE- EM PN GEK112031	CF34-8E	3066T16G05	CASE-FAN BLD	72-23-01	Overhaul, Repair, Inspection, Testing
899	11/Jun/24	Limited Engine	GE- EM PN GEK112031	CF34-8E	3066T16G07	CASE-FAN BLD	72-23-01	Overhaul, Repair, Inspection, Testing
900	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	45P1082	BOOSTER IGV ASSY	72-21-09	Overhaul, Repair, Inspection, Testing
901	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	45P1065	STAGE 2 VANE ASSY	72-21-09	Overhaul, Repair, Inspection, Testing
902	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	45P1169	STAGE 3 VANE ASSY	72-21-09	Overhaul, Repair, Inspection, Testing
903	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	45P1075	STAGE 4 VANE ASSY	72-21-09	Overhaul, Repair, Inspection, Testing
904	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	2050M56P01	FAN BLADE REAINER	72-21-01	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
905	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	2050M56P02	FAN BLADE REAINER	72-21-01	Overhaul, Repair, Inspection, Testing
906	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	2050M56P04	FAN BLADE REAINER	72-21-01	Overhaul, Repair, Inspection, Testing
907	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	2489M01P01	FAN BLADE REAINER	72-21-01	Overhaul, Repair, Inspection, Testing
908	11/Jun/24	Limited Engine	GE- EM PN GEK105091	CF34-8C	4115T35P01	RING-AXS-B	72-64-19	Overhaul, Repair, Inspection, Testing
909	11/Jun/24	Limited Engine	GE- EM PN GEK105091	CF34-8C	4115T35P02	RING-AXS-B	72-64-19	Overhaul, Repair, Inspection, Testing
910	11/Jun/24	Limited Engine	GE- EM PN GEK105091	CF34-8C	4115T36P01	RING-AXS-D	72-64-19	Overhaul, Repair, Inspection, Testing
911	11/Jun/24	Limited Engine	GE- EM PN GEK105091	CF34-8C	4115T36P02	RING-AXS-D	72-64-19	Overhaul, Repair, Inspection, Testing
912	11/Jun/24	Limited Engine	GE- EM PN GEK105091	CF34-8C	4115T37P01	RING-AXS-G	72-64-19	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
913	11/Jun/24	Limited Engine	GE- EM PN GEK105091	CF34-8C	4115T37P02	RING-AXS-F	72-64-19	Overhaul, Repair, Inspection, Testing
914	11/Jun/24	Limited Engine	GE- EM PN GEK105091	CF34-8C	4115T38P01	RING-AXS E	72-64-19	Overhaul, Repair, Inspection, Testing
915	11/Jun/24	Limited Engine	GE- EM PN GEK105091	CF34-8C	4115T38P02	RING-AXS E	72-64-19	Overhaul, Repair, Inspection, Testing
916	11/Jun/24	Limited Engine	GE- EM PN GEK105091	CF34-8C	4115T39P01	RING-AXS-C	72-64-19	Overhaul, Repair, Inspection, Testing
917	11/Jun/24	Limited Engine	GE- EM PN GEK105091	CF34-8C	4115T39P02	RING-AXS-E/G	72-64-19	Overhaul, Repair, Inspection, Testing
918	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	2072M88G01	FAIRING, STRUT	72-23-23	Overhaul, Repair, Inspection, Testing
919	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	2072M88G02	FAIRING, STRUT	72-23-23	Overhaul, Repair, Inspection, Testing
920	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	2072M88G03	FAIRING, STRUT	72-23-23	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
921	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	2050M62P01	SPACER FAN BLADE	72-21-03	Overhaul, Repair, Inspection, Testing
922	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	2050M62P02	SPACER FAN BLADE	72-21-03	Overhaul, Repair, Inspection, Testing
923	11/Jun/24	Limited Engine	GE- EM PN GEK112081	CF34-10E	2050M62P03	SPACER FAN BLADE	72-21-03	Overhaul, Repair, Inspection, Testing
924	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1292M13G03	PLATFORM ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
925	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1292M13G04	PLATFORM ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
926	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1292M13G05	PLATFORM ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
927	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1292M13G06	PLATFORM ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
928	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1301M28G04	PLATFORM-ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
929	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1301M28G05	PLATFORM-ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
930	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1301M28G06	PLATFORM-ENGINE MOUNT (*)	71-21-01	Overhaul, Repair, Inspection, Testing
931	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1301M28G07	PLATFORM-ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
932	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1301M28G08	PLATFORM-ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
933	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1459M70G06	PLATFORM ASSY ENG. MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
934	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1459M70P01	PLATFORM ENG. MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
935	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1806M79G01	YOKE ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
936	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1806M79G02	YOKE ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
937	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1806M80G01	PLATFORM, FWD ENG. MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
938	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1806M87G01	PLATFORM-ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
939	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1806M88G01	PLATFORM ASSY ENG. MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
940	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1846M24G02	PLATFORM ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
941	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1846M24G03	PLATFORM ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
942	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1846M24G04	PLATFORM ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
943	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1846M24G05	PLATFORM ASSY ENG. MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
944	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1846M24G06	PLATFORM ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
945	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1846M24G07	PLATFORM ASSY ENG. MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
946	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9383M43G08	YOKE-ENGINE MOUNT ASSY	71-21-01	Overhaul, Repair, Inspection, Testing
947	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9383M43G10	YOKE-ENGINE MOUNT ASSY	71-21-01	Overhaul, Repair, Inspection, Testing
948	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9383M43G11	YOKE-ENGINE MOUNT ASSY (*)	71-21-01	Overhaul, Repair, Inspection, Testing
949	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9383M43G13	YOKE-ENGINE MOUNT ASSY	71-21-01	Overhaul, Repair, Inspection, Testing
950	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	9383M43G14	YOKE-ENGINE MOUNT ASSY	71-21-01	Overhaul, Repair, Inspection, Testing
951	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1806M80P01	PLATFORM-ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing
952	11/Jun/24	Limited Engine	GE - EM PN GEK 92451	CF6-80C2	1806M87P01	PLATFORM ENGINE MOUNT	71-21-01	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
953	11/Jun/24	Limited Engine	IAE - CMM PN 2A4412	V2500	3A1745	SUPPORT ASSY	75-24-49	Overhaul, Repair, Inspection, Testing
954	11/Jun/24	Limited Engine	IAE - CMM PN 2A4412	V2500	3A1749	SUPPORT ASSY	75-24-49	Overhaul, Repair, Inspection, Testing
955	11/Jun/24	Limited Engine	IAE - CMM PN 2A4412	V2500	3A1752	SUPPORT ASSY	75-24-49	Overhaul, Repair, Inspection, Testing
956	11/Jun/24	Limited Engine	IAE - CMM PN 2A4412	V2500	3A1755	SUPPORT ASSY	75-24-49	Overhaul, Repair, Inspection, Testing
957	11/Jun/24	Limited Engine	IAE - CMM PN 2A4412	V2500	3A1759	SUPPORT ASSY	75-24-49	Overhaul, Repair, Inspection, Testing
958	11/Jun/24	Limited Engine	IAE - CMM PN 2A4412	V2500	3A1762	SUPPORT ASSY	75-24-49	Overhaul, Repair, Inspection, Testing
959	11/Jun/24	Limited Engine	IAE - CMM PN 2A4412	V2500	3A2320	SUPPORT ASSY	75-24-49	Overhaul, Repair, Inspection, Testing
960	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	1845M90G04	DAMPER STATIONARY LPT	72-54-22	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
961	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	5A0015	CONE,ASSY INLET	72-38-11	Overhaul, Repair, Inspection, Testing
962	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	5A1452	CONE,ASSY INLET	72-38-11	Overhaul, Repair, Inspection, Testing
963	11/Jun/24	Limited Engine	IAE - EM PN 2A4407	V2500	5A1733	CONE,ASSY INLET	72-38-11	Overhaul, Repair, Inspection, Testing
964	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	1688M99P08	BUSHING GRBX LINK FAN FR	72-64-08	Overhaul, Repair, Inspection, Testing
965	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	1768M25P06	BUSHING	72-64-08	Overhaul, Repair, Inspection, Testing
966	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	1770M21G07	LINK ASSY RIGHT SIDE	72-64-08	Overhaul, Repair, Inspection, Testing
967	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	1770M21G09	LINK ASSY RIGHT SIDE	72-64-08	Overhaul, Repair, Inspection, Testing
968	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	1770M22G03	LINK LEFT SIDE	72-64-08	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
969	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	1995M10P01	AXE GRBX AXL MT	72-64-08	Overhaul, Repair, Inspection, Testing
970	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	1995M11P01	AXE FAN FR AXL MT	72-64-08	Overhaul, Repair, Inspection, Testing
971	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	1995M13P01	AXE LINK VERTICAL	72-64-08	Overhaul, Repair, Inspection, Testing
972	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	1995M14P01	AXE LINK VERTICAL	72-64-08	Overhaul, Repair, Inspection, Testing
973	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2205M44G01	LINK LEFT SIDE ASSY OF	72-64-08	Overhaul, Repair, Inspection, Testing
974	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2205M45G01	LINK ASSY RIGHT SIDE	72-64-08	Overhaul, Repair, Inspection, Testing
975	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2205M46G01	LINK LEFT SIDE	72-64-08	Overhaul, Repair, Inspection, Testing
976	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2205M47P01	AXE LINK VERTICAL	72-64-08	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
977	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2206M23G02	LINK LEFT SIDE ASSY OF	72-64-08	Overhaul, Repair, Inspection, Testing
978	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2206M23G03	LINK LEFT SIDE ASSY OF	72-64-08	Overhaul, Repair, Inspection, Testing
979	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2206M31G01	LINK LATERAL MOUNT SIDE	72-64-08	Overhaul, Repair, Inspection, Testing
980	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2206M31G02	LINK LATERAL MOUNT SIDE	72-64-08	Overhaul, Repair, Inspection, Testing
981	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2206M32G01	LINK AXIAL ASSY OF	72-64-08	Overhaul, Repair, Inspection, Testing
982	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2206M32G02	LINK AXIAL ASSY OF	72-64-08	Overhaul, Repair, Inspection, Testing
983	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2206M53P01	BUSHING	72-64-08	Overhaul, Repair, Inspection, Testing
984	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	2206M54P01	AXIS LINK MOUNT TOP AXIAL	72-64-08	Overhaul, Repair, Inspection, Testing

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

Num	Input Date	Rating	OEM - Technical Data	Engine Type	Part Number	Part Description	ATA Code	Maintenance Level
985	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	J1494P07A	BOLT-MACHINE, DOUBLE HEX HD	72-64-08	Overhaul, Repair, Inspection, Testing
986	11/Jun/24	Limited Engine	GE - EM PN GEK109993	GE90-100	J644P07A	BOLT-MACHINE, DOUBLE HEX HD	72-64-08	Overhaul, Repair, Inspection, Testing
987	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5W2046	SUPPORT , A/O NO.2 BEARING	72-32-17	Overhaul, Repair, Inspection, Testing
988	11/Jun/24	Limited Engine	IAE - EM PN 2A4407 and PN 2A4416	V2500	5W2253	SUPPORT , A/O NO.2 BEARING	72-32-17	Overhaul, Repair, Inspection, Testing