



U.S. Department
of Transportation
**Federal Aviation
Administration**

Aviation Safety
New York International Field Office

15930 Rockaway Boulevard
Room 504
Jamaica NY 11434

August 28, 2024

Ms. Jelena Zelenovic
Quality Manager
MTU Maintenance Serbia d.o.o.
1 Cetvrta Centralna Radna Street
22330, Nova Pazova
Serbia

Dear Ms. Zelenovic:

The New York International Field Office accepts Capability List, CL-MTUBEG-FAA, Revision 15, dated August 8, 2024, for certificate MTUY154E per 14 CFR §145.215(a).

Please contact this office if you have any questions.

Sincerely,

AGAPIOS
HATZIPAVLOU  Digitally signed by AGAPIOS HATZIPAVLOU
Date: 2024.08.28 09:41:04 -0400

Agapios Hatzipavlou
Principal Maintenance Inspector

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|------------------------|----------|---------------------------------------|
| 1 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A6549 | CASE,ASSY,STG.9,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 2 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1433 | CASE,ASSY,STG.9,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 3 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3653 | RING,STG.9-R/PATH,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 4 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4163 | RING,STG.9-R/PATH,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 5 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A6550 | CASE,ASSY,STG.10,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 6 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1434 | CASE,ASSY,STG.10,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 7 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3654 | RING STG.10-R/PATH,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 8 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4164 | RING STG.10-R/PATH,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|------------------------|----------|---------------------------------------|
| 9 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A6551 | CASE ASSY,STG.11,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 10 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7531 | CASE,ASSY,STG.11,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 11 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1435 | CASE,ASSY,STG.11,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 12 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3655 | RING,STG.11-R/PATH,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 13 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4297 | RING,STG.11-R/PATH,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 14 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A6552 | CASE, ASSY, STG.12,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 15 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1436 | CASE, ASSY, STG.12,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 16 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3656 | RING,STG.12-R/PATH,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------------|-------------|-------------|------------------------|----------|--|
| 17 | 14/Nov/22 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4166 | RING,STG.12-R/PATH,HPC | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 18 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1221 | BLADE,STG.2,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 19 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1222 | BLADE,STG.2,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 20 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1223 | BLADE,STG.2,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 21 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1224 | BLADE,STG.2,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 22 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1231 | BLADE,STG.3,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 23 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1232 | BLADE,STG.3,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 24 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1233 | BLADE,STG.3,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|---------------|------------------|----------|--|
| 25 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1234 | BLADE,STG.3,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 26 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1241 | BLADE,STG.4,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 27 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1242 | BLADE,STG.4,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 28 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1243 | BLADE,STG.4,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 29 | 14/Nov/22 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 45P1244 | BLADE,STG.4,LPC | 72-21-07 | Overhaul, Repair, Inspection, Testing |
| 30 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 01R30B4285-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 31 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B2855-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 32 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B2856-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|------------------|----------|--|
| 33 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B3865-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 34 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B4285-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 35 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B4934-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 36 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B5117-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 37 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B6948-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 38 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3170-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 39 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4901-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 40 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4977-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|---------------------|-----------------------------|-------------|-------------|-------------------|----------|---------------------------------------|
| 41 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B5173-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 42 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B6135-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 43 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30P1711-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 44 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30P2401-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 45 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30P2661-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 46 | 14/Nov/22 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30P2929-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 47 | 14/Nov/22 | Limited Accessories | IAE - CMM PN 2A4412 | V2500 | 3A2337 | SUPPORT-ASSY,NO.1 | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 48 | 14/Nov/22 | Limited Accessories | IAE - CMM PN 2A4412 | V2500 | 3A2350 | SUPPORT-ASSY,NO.2 | 75-24-49 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|---------------------|----------------------|-------------|---------------|-------------------|----------|---------------------------------------|
| 49 | 14/Nov/22 | Limited Accessories | IAE - CMM PN 2A4412 | V2500 | 3A2355 | SUPPORT-ASSY,NO.3 | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 50 | 14/Nov/22 | Limited Accessories | IAE - CMM PN 2A4412 | V2500 | 3A2358 | SUPPORT-ASSY,NO.4 | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 51 | 14/Nov/22 | Limited Accessories | IAE - CMM PN 2A4412 | V2500 | 3A2362 | SUPPORT-ASSY,NO.5 | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 52 | 14/Nov/22 | Limited Accessories | IAE - CMM PN 2A4412 | V2500 | 3A2365 | SUPPORT-ASSY,NO.6 | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 53 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 335-191-202-0 | LPC BLADE STG. 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 54 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 335-191-203-0 | LPC BLADE STG. 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 55 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 335-191-204-0 | LPC BLADE STG. 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 56 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 335-191-205-0 | LPC BLADE STG. 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|---------------|------------------|----------|--|
| 57 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 335-191-302-0 | LPC BLADE STG. 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 58 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 335-191-303-0 | LPC BLADE STG. 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 59 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 335-191-304-0 | LPC BLADE STG. 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 60 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 335-191-305-0 | LPC BLADE STG. 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 61 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-201-0 | LPC BLADE STG. 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 62 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-202-0 | LPC BLADE STG. 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 63 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-203-0 | LPC BLADE STG. 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 64 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-204-0 | LPC BLADE STG. 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|---------------|------------------|----------|--|
| 65 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-301-0 | LPC BLADE STG. 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 66 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-302-0 | LPC BLADE STG. 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 67 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-303-0 | LPC BLADE STG. 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 68 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-304-0 | LPC BLADE STG. 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 69 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-401-0 | LPC BLADE STG. 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 70 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-402-0 | LPC BLADE STG. 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 71 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-403-0 | LPC BLADE STG. 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 72 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-404-0 | LPC BLADE STG. 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------------|-------------|---------------|---------------------------------|----------|--|
| 73 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-409-0 | LPC BLADE STG. 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 74 | 23/Feb/23 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-057-410-0 | LPC BLADE STG. 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 75 | 23/Feb/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30P2021-01 | FAN BLADE | 72-31-21 | Overhaul, Repair, Inspection, Testing |
| 76 | 23/Feb/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5A0865 | BLADE, A/O STAGE 2.3 LPC | 72-32-82 | Overhaul, Repair, Inspection, Testing |
| 77 | 23/Feb/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5A1445 | BLADE, A/O STG.1.5 LPC | 72-32-82 | Overhaul, Repair, Inspection, Testing |
| 78 | 23/Feb/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5R0091 | BLADE, A/O STAGE 2.0 LPC | 72-32-82 | Overhaul, Repair, Inspection, Testing |
| 79 | 23/Feb/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5R0180 | BLADE, A/O STAGE 2.5 LPC | 72-32-82 | Overhaul, Repair, Inspection, Testing |
| 80 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3471 | HPC STAGE 5 HALF SHROUD ASSY | 72-41-33 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|--------------------------------|----------|---------------------------------------|
| 81 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7563 | HPC STAGE 5 HALF SHROUD ASSY | 72-41-33 | Overhaul, Repair, Inspection, Testing |
| 82 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1158 | HPC STAGE 5 HALF SHROUD ASSY | 72-41-33 | Overhaul, Repair, Inspection, Testing |
| 83 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3467 | HPC STAGE 3 HALF SHROUD ASSY | 72-41-33 | Overhaul, Repair, Inspection, Testing |
| 84 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7719 | HPC STAGE 3 HALF SHROUD ASSY | 72-41-33 | Overhaul, Repair, Inspection, Testing |
| 85 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1156 | HPC STAGE 3 HALF SHROUD ASSY | 72-41-33 | Overhaul, Repair, Inspection, Testing |
| 86 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A1093 | HPC STAGE 3 HALF SEAL RING | 72-41-33 | Overhaul, Repair, Inspection, Testing |
| 87 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3025 | HPC STAGE 5 ROTOR PATH SEGMENT | 72-41-31 | Overhaul, Repair, Inspection, Testing |
| 88 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3976 | HPC STAGE 5 ROTOR PATH SEGMENT | 72-41-31 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|--------------------------------|----------|---------------------------------------|
| 89 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4349 | HPC STAGE 5 ROTOR PATH SEGMENT | 72-41-31 | Overhaul, Repair, Inspection, Testing |
| 90 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7471 | HPC STAGE 5 ROTOR PATH SEGMENT | 72-41-31 | Overhaul, Repair, Inspection, Testing |
| 91 | 5/Apr/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7573 | HPC STAGE 5 ROTOR PATH SEGMENT | 72-41-31 | Overhaul, Repair, Inspection, Testing |
| 92 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9805 | LPC BLADE STAGE 5 | 72-31-16 | Overhaul, Repair, Inspection, Testing |
| 93 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9905 | LPC BLADE STAGE 5 | 72-31-16 | Overhaul, Repair, Inspection, Testing |
| 94 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B3705 | LPC BLADE STAGE 5 | 72-31-16 | Overhaul, Repair, Inspection, Testing |
| 95 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B4405 | LPC BLADE STAGE 5 | 72-31-16 | Overhaul, Repair, Inspection, Testing |
| 96 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9804 | LPC BLADE STAGE 4 | 72-31-15 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 97 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9904 | LPC BLADE STAGE 4 | 72-31-15 | Overhaul, Repair, Inspection, Testing |
| 98 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B3404 | LPC BLADE STAGE 4 | 72-31-15 | Overhaul, Repair, Inspection, Testing |
| 99 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B3704 | LPC BLADE STAGE 4 | 72-31-15 | Overhaul, Repair, Inspection, Testing |
| 100 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9802 | LPC BLADE STAGE 2 | 72-31-13 | Overhaul, Repair, Inspection, Testing |
| 101 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9902 | LPC BLADE STAGE 2 | 72-31-13 | Overhaul, Repair, Inspection, Testing |
| 102 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B4102 | LPC BLADE STAGE 2 | 72-31-13 | Overhaul, Repair, Inspection, Testing |
| 103 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6702 | LPC BLADE STAGE 2 | 72-31-13 | Overhaul, Repair, Inspection, Testing |
| 104 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9803 | LPC BLADE STAGE 3 | 72-31-14 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 105 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9903 | LPC BLADE STAGE 3 | 72-31-14 | Overhaul, Repair, Inspection, Testing |
| 106 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B3703 | LPC BLADE STAGE 3 | 72-31-14 | Overhaul, Repair, Inspection, Testing |
| 107 | 25/Apr/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B4103 | LPC BLADE STAGE 3 | 72-31-14 | Overhaul, Repair, Inspection, Testing |
| 108 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M30P01 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 109 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M30P02 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 110 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M30P03 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 111 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M30P04 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 112 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M36P01 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 113 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M36P02 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 114 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M36P03 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 115 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M36P04 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 116 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M37P01 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 117 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M37P02 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 118 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M37P03 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 119 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M37P04 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 120 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M37P05 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 121 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M37P06 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 122 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M38P01 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 123 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M38P02 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 124 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M38P03 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 125 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M38P04 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 126 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M38P05 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 127 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M38P06 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 128 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M72P01 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 129 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M72P02 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 130 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M72P03 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 131 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M72P04 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 132 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M73P01 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 133 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M73P02 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 134 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M73P03 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 135 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M73P04 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 136 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M74P01 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 137 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M74P02 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 138 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M74P03 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 139 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M74P04 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 140 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M75P01 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 141 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M75P02 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 142 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M75P03 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 143 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M75P04 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 144 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M92P01 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 145 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M92P01W | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 146 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M92P02 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 147 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M92P03 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 148 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M92P04 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 149 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M92P05 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 150 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M93P01 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 151 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M93P02 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 152 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M93P03 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 153 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M93P04 | LPC BLADE STAGE 3 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 154 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M94P01 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 155 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M94P02 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 156 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M94P03 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 157 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M94P04 | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 158 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M95P01 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 159 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M95P01W | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 160 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M95P02 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------|-------------|-------------|--------------------------------|----------|--|
| 161 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M95P03 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 162 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M95P04 | LPC BLADE STAGE 5 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 163 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1704M43P05 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 164 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1704M43P06 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 165 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1704M43P07 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 166 | 25/Apr/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1704M43P08 | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 167 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3044315-01 | COVER, OIL PRESS ADJ..VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 168 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3045286-01 | ADAPTER, FUEL HEATER | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------|-------------|-------------|----------------------------|----------|--|
| 169 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3053049-01 | COVER, ALTERNATOR PAD | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 170 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3073197-01 | ADAPTER , FUEL HEATER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 171 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3078358-01 | COVER, COLD START VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 172 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3109908-01 | ADAPTER, CHIP DETECTOR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 173 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3113645-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 174 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3113645-02 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 175 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3113724-01 | COVER, OIL FILTER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 176 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3114458-01 | COVER, SHUT OFF VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------|-------------|-------------|--------------------------------|----------|--|
| 177 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3114872-01 | COVER, INPUT SHAFT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 178 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3114956-01 | COVER, HEATER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 179 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3115784-01 | HOUSING, COLD START VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 180 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3116006-01 | COVER, OIL PRESS ADJ..VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 181 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3116456-01 | COVER, SHUT OFF VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 182 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3116516-01 | COVER, PLAIN, 2-HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 183 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3116517-01 | COVER, PLAIN, 2-HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 184 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3120876-01 | COVER, COLD START VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|-------------------------------|----------|---------------------------------------|
| 185 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3121535-01 | COVER, OIL PRESS REG VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 186 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | ST3387-01 | COVER, SHIPP. STARTER GENERA. | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 187 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | ST3389-01 | COVER, ACC DRIVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 188 | 25/Apr/23 | Limited Engine | PWC - CIR MANUAL PN 304877 | PW200 | 3116000-01 | ELBOW, BREATHER TUBE | 72-09-10 | Overhaul, Repair, Inspection, Testing |
| 189 | 26/Apr/23 | Limited Engine | GE - EM PN GEK 112031 | CF34-8E | 4114T15P02 | FAN BLADE | 72-21-13 | Overhaul, Repair, Inspection, Testing |
| 190 | 26/Apr/23 | Limited Engine | GE - EM PN GEK 112031 | CF34-8E | 4114T31G01 | FAN BLADE | 72-21-13 | Overhaul, Repair, Inspection, Testing |
| 191 | 26/Apr/23 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 2225M27P02 | FAN BLADE | 72-21-04 | Overhaul, Repair, Inspection, Testing |
| 192 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B4270-01 | CONE COMPRESSOR INLET | 72-31-40 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|---------------------------|----------|--|
| 193 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B5082-01 | CONE COMPRESSOR INLET | 72-31-40 | Overhaul, Repair, Inspection, Testing |
| 194 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B5745-01 | CONE COMPRESSOR INLET | 72-31-40 | Overhaul, Repair, Inspection, Testing |
| 195 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1340-01 | NUT BEARING RETAINING | 72-09-98 | Overhaul, Repair, Inspection, Testing |
| 196 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2023-01 | NUT TIE ROD RETAINING | 72-09-98 | Overhaul, Repair, Inspection, Testing |
| 197 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3068-01 | NUT RETAINING FAN HUB | 72-09-98 | Overhaul, Repair, Inspection, Testing |
| 198 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4015-01 | NUT TIE ROD RETAINING | 72-09-98 | Overhaul, Repair, Inspection, Testing |
| 199 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4016-01 | NUT | 72-09-98 | Overhaul, Repair, Inspection, Testing |
| 200 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B3331-01 | ADAPTER ASSY, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|------------------------------------|----------|--|
| 201 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B3364-01 | PLUG, AGB | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 202 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B4804-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 203 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B4929-01 | ADAPTER ASSY,AGB,BREATH ER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 204 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B5110-01 | ADAPTER,TUBE,BREATH ER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 205 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B6833-01 | ADAPTER,TUBE,BREATH ER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 206 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B6839-01 | ADAPTER ASSY, BREATH ER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 207 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B6842-01 | CONNECTOR ASSY,AGB,BREATH ER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 208 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B7349-01 | ADAPTER ASSEMBLY, STRAINER | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|-------------------------------|----------|--|
| 209 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B7434-01 | ADAPTER, STRAINER, ASSY | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 210 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B7456-01 | ADAPTER ASSEMBLY, STRAINER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 211 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C1245-01 | ADAPTER, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 212 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C1485-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 213 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C1622-01 | PLUG PLAIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 214 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C2808-01 | ADAPTER OIL SCAV. | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 215 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C2867-01 | COVER PLAIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 216 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C3620-01 | COVER, AGB, LOWER | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|-----------------------------|----------|--|
| 217 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C3818-01 | ADAPTER, RESTRICTOR, | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 218 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C4266-01 | ADAPTER ASSY, HYDR. | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 219 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C4271-01 | TUBE, VENT, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 220 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C5035-01 | ADAPTER ASSY, HYDR. | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 221 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C5300-01 | ADAPTER, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 222 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30P1367-01 | TUBE, SCAVENGE, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 223 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30P1460-01 | COVER ASSY, P2.8/P3 AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 224 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30P2701-01 | ADAPTER, AC GENERATOR | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|---------------------------|----------|---------------------------------------|
| 225 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1120-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 226 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1202-01 | PLUG, RELIEF VALVE, BALL | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 227 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1391-01 | PLUG, PLAIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 228 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1394-01 | COVER, PACKING, 2-HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 229 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1741-01 | COVER, PACKING, 2-HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 230 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1743-01 | COVER, PACKING, TWO HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 231 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1748-01 | ELBOW, TUBE TO BOSS | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 232 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1771-01 | ADAPTER, STRAIGHT, 2 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 233 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2541-01 | ADAPTER, FUEL FILTER DRAIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 234 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2542-01 | ADAPTER, FUEL TEMP. SENSOR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 235 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2543-01 | ADAPTER, AIR BLEED | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 236 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2560-01 | ADAPTER ASSY, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 237 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3599-01 | COVER, PLAIN, 4-HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 238 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3616-01 | PLATE, BLANKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 239 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3617-01 | PLATE, BLANKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 240 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3751-01 | COVER, PLAIN, 4-HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|--------------------------|----------|---------------------------------------|
| 241 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4127-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 242 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4129-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 243 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4161-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 244 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4271-01 | ADAPTER ASSY, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 245 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B5141-01 | ADAPTER ASSY, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 246 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B5409-01 | PLUG, RELIEF VALVE, BALL | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 247 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B5537-01 | ADAPTER ASSY, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 248 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B6137-01 | ADAPTER ASSY, 3 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|--------------------------------------|----------|---------------------------------------|
| 249 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B6163-01 | ADAPTER ASSY, BLEED VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 250 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | AS3223 | COVER-PLATE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 251 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | MS9954-04 | PLUG-MACHINE THD | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 252 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | ST3388-01 | COVER, ENGINE, ACC. DRIVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 253 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | ST3687-01 | COVER, PACKING, ONE GROOVE, TWO HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 254 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | ST3816-01 | COVER, PLAIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 255 | 5/May/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | ST6151-01 | COVER, PLAIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 256 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1347M56G01 | LPC VANE STG 5 | 72-23-22 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------|----------|--|
| 257 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1347M56G02 | LPC VANE STG 5 | 72-23-22 | Overhaul, Repair, Inspection, Testing |
| 258 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M25G09 | LPC VANE STG 5 | 72-23-22 | Overhaul, Repair, Inspection, Testing |
| 259 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M25G10 | LPC VANE STG 5 | 72-23-22 | Overhaul, Repair, Inspection, Testing |
| 260 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M25G13 | LPC VANE STG 5 | 72-23-22 | Overhaul, Repair, Inspection, Testing |
| 261 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M25G14 | LPC VANE STG 5 | 72-23-22 | Overhaul, Repair, Inspection, Testing |
| 262 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M22G04 | LPC VANE STG 2 | 72-25-02 | Overhaul, Repair, Inspection, Testing |
| 263 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M22G05 | LPC VANE STG 2 | 72-25-02 | Overhaul, Repair, Inspection, Testing |
| 264 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M22G08 | LPC VANE STG 2 | 72-25-02 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|-----------------------|----------|--|
| 265 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M22G09 | LPC VANE STG 2 | 72-25-02 | Overhaul, Repair, Inspection, Testing |
| 266 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M23G05 | LPC VANE STG 3 | 72-25-02 | Overhaul, Repair, Inspection, Testing |
| 267 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M23G09 | LPC VANE STG 3 | 72-25-02 | Overhaul, Repair, Inspection, Testing |
| 268 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M24G04 | LPC VANE STG 4 | 72-25-02 | Overhaul, Repair, Inspection, Testing |
| 269 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M24G05 | LPC VANE STG 4 | 72-25-02 | Overhaul, Repair, Inspection, Testing |
| 270 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M24G08 | LPC VANE STG 4 | 72-25-02 | Overhaul, Repair, Inspection, Testing |
| 271 | 8/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M24G09 | LPC VANE STG 4 | 72-25-02 | Overhaul, Repair, Inspection, Testing |
| 272 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3041944-01 | TUBE ASSY, OIL, INLET | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|-----------------------------|----------|---------------------------------------|
| 273 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3042767-01 | COVER, AGB, LOWER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 274 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052405-01 | ADAPTER, STRAIGHT, 2 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 275 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052445-01 | ADAPTER, STRAIGHT, 2 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 276 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052503-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 277 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052544-01 | COVER PLATE, FAIRING, FRONT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 278 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052555-01 | COVER, BEARING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 279 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052572-01 | COVER, VALVE, COLD START | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 280 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052579-01 | COVER, PACKING, 3 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|-----------------------------|----------|---------------------------------------|
| 281 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052593-01 | COVER, PACKING, 4 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 282 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052594-01 | COVER, PACKING, 1GRV, 2HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 283 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052599-01 | COVER PLATE, FAIRING, REAR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 284 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052613-01 | TUBE, SUPPORT, IGNITER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 285 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052621-01 | ADAPTER, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 286 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052623-01 | COVER, PLAIN, 4 HOLES | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 287 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052625-01 | COVER, TUBE, P3 AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 288 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3052930-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|-----------------------------|----------|---------------------------------------|
| 289 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3053033-01 | PLUG, SHAFT, LC | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 290 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3053035-01 | COVER, PACKING, 1GRV, 2HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 291 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3053047-01 | COVER, PACKING, 1GRV, 2HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 292 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3053272-01 | RESTRICTOR, OIL | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 293 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3055234-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 294 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3055235-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 295 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3055338-01 | ADAPTER, TUBE TO BOSS | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 296 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3059060-01 | ATTENUATOR ASSY | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|--------------------------------|----------|--|
| 297 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3059062-01 | ADAPTER, ATTENUATOR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 298 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3059859-01 | COVER, SEAL, GEARSHAFT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 299 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3071800-01 | ADAPTER, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 300 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 3073762-01 | COVER PLATE, FAIRING, FRONT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 301 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J1493-01 | COVER PLATE, FAIRING, REAR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 302 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J1602-01 | ADAPTER, TUBE TO BOSS | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 303 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J1724-01 | COVER, AGB, LOWER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 304 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J1734-01 | TUBE ASSY, VENT, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|-----------------------|----------|--|
| 305 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J1747-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 306 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J1772-01 | COVER, PLAIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 307 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J1807-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 308 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J1808-01 | COVER, AIR, CABIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 309 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2013-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 310 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2156-01 | COVER, PLAIN, 4 HOLES | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 311 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2382-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 312 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2383-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|---------------------------|----------|--|
| 313 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2385-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 314 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2386-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 315 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2615-01 | ATTENUATOR ASSY | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 316 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2616-01 | ADAPTER, ATTENUATOR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 317 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2785-01 | COVER, SEAL, GEARSHAFT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 318 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2858-01 | ADAPTER, TRANSFORMER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 319 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J2979-01 | ADAPTER, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 320 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3064-01 | TUBE ASSY, OIL, INLET | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|--------------------------------|----------|--|
| 321 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3182-01 | COVER PLATE, FAIRING, FRONT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 322 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3183-01 | COVER PLATE, FAIRING, FRONT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 323 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3520-01 | PLUG, INTERMEDIATE CASE HSG | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 324 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3556CL | DUMMY TUBE, VENT, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 325 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3556CL01 | TUBE ASSY, VENT, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 326 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3556CL02 | TUBE ASSY, VENT, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 327 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3556CL03 | TUBE ASSY, VENT, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 328 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3556CL04 | TUBE ASSY, VENT, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|--------------------------------|----------|--|
| 329 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3556CL05 | TUBE ASSY, VENT, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 330 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 30J3556CL06 | TUBE ASSY, VENT, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 331 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1225-01 | COVER PLATE, FAIRING, FRONT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 332 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1297-01 | PLATE, RETAINING, BEARING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 333 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1301-01 | COVER, BEARING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 334 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1370-01 | PLUG, SHAFT, LC | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 335 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1460-01 | COVER, VALVE, COLD START | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 336 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1477-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|--------------------------------|----------|--|
| 337 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1501-01 | COVER, PACKING, 3 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 338 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1669-01 | ADAPTER, STRAIGHT, 2 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 339 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1672-01 | COVER, O/S CONTR. LINKAGE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 340 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1785-01 | COVER, PACKING, 4 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 341 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1790-01 | COVER, PACKING, 1GRV, 2HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 342 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1831-01 | COVER PLATE, FAIRING, REAR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 343 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J1899-01 | ADAPTER, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 344 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2062-01 | COVER, AIR, CABIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|-----------------------------|----------|---------------------------------------|
| 345 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2147-01 | COVER PLATE, FAIRING, FRONT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 346 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2249-01 | COVER, PACKING, 1GRV, 2HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 347 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2267-01 | TUBE ASSY, VENT, OIL TANK | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 348 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2306-01 | TUBE, SUPPORT, IGNITER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 349 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2325-01 | COVER, PLAIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 350 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2383-01 | ADAPTER, BREATHER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 351 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2403-01 | COVER, PLAIN, 4 HOLES | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 352 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2455-01 | COVER, TUBE, P3 AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|---------------------------|----------|---------------------------------------|
| 353 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2561-01 | TUBE ASSY, OIL, INLET | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 354 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2674-01 | ADAPTER, STRAIGHT, 2 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 355 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2742-01 | COVER, AGB, LOWER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 356 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2817-01 | COVER ASSY, TUBE, AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 357 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | 31J2890-01 | BRACKET, ACCELEROMETER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 358 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | ST3342-01 | PLUG, MACHINE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 359 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | ST3525-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 360 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | ST3526-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|---------------------------|----------|---------------------------------------|
| 361 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | ST3552-01 | PLUG, BLANKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 362 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | ST3613-06 | ADAPTER, TUBE TO BOSS | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 363 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | ST3661-01 | COVER, O/S CONTR. LINKAGE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 364 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | ST3890-01 | COVER, PLAIN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 365 | 8/May/23 | Limited Engine | PWC - CIR MANUAL PN 30J2306 | PW500 | ST6401-01 | COVER, 1 GROOVE, 2 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 366 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3390 | HPC STAGE 11 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 367 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4328 | HPC STAGE 11 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 368 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3387 | HPC STAGE 8 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|-------------------|----------|---------------------------------------|
| 369 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4324 | HPC STAGE 8 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 370 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3388 | HPC STAGE 9 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 371 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4311 | HPC STAGE 9 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 372 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4326 | HPC STAGE 9 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 373 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A6511 | HPC STAGE 9 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 374 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3389 | HPC STAGE 10 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 375 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4526 | HPC STAGE 10 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 376 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A5436 | HPC STAGE 10 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|--------------------------------|----------|---------------------------------------|
| 377 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A5438 | HPC STAGE 10 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 378 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A5624 | HPC STAGE 10 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 379 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A5676 | HPC STAGE 10 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 380 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A6512 | HPC STAGE 10 CASE | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 381 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4348 | HPC STAGE 4 ROTOR PATH SEGMENT | 72-41-31 | Overhaul, Repair, Inspection, Testing |
| 382 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7470 | HPC STAGE 4 ROTOR PATH SEGMENT | 72-41-31 | Overhaul, Repair, Inspection, Testing |
| 383 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A1427 | HPC STAGE 4 HALF SEAL RING | 72-41-33 | Overhaul, Repair, Inspection, Testing |
| 384 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3469 | HPC STAGE 4 HALF SHROUD ASSY | 72-41-33 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|--------------------------------|----------|---------------------------------------|
| 385 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7561 | HPC STAGE 4 HALF SHROUD ASSY | 72-41-33 | Overhaul, Repair, Inspection, Testing |
| 386 | 8/May/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1175 | HPC STAGE 4 HALF SHROUD ASSY | 72-41-33 | Overhaul, Repair, Inspection, Testing |
| 387 | 12/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M93P01W | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 388 | 13/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1336M94P01W | LPC BLADE STAGE 4 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 389 | 14/May/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1704M43P05W | LPC BLADE STAGE 2 | 72-21-02 | Overhaul, Repair, Inspection, Testing |
| 390 | 13/Jun/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4723 | HPC Stage 6 Rotor Path Segment | 72-41-31 | Overhaul, Repair, Inspection, Testing |
| 391 | 13/Jun/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A5994 | HPC Stage 6 Rotor Path Segment | 72-41-31 | Overhaul, Repair, Inspection, Testing |
| 392 | 13/Jun/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7576 | HPC Stage 6 Rotor Path Segment | 72-41-31 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|---------------------------|----------|---------------------------------------|
| 393 | 13/Jun/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5R0479 | BRACKET, A/O A3 G/B MOUNT | 72-00-60 | Overhaul, Repair, Inspection, Testing |
| 394 | 13/Jun/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5R0480 | BRACKET, A/O A3 G/B MOUNT | 72-00-60 | Overhaul, Repair, Inspection, Testing |
| 395 | 13/Jun/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5R0482 | BRACKET, A/O ASSY | 72-00-60 | Overhaul, Repair, Inspection, Testing |
| 396 | 13/Jun/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5R0483 | BRACKET, A/O A2 G/B | 72-00-60 | Overhaul, Repair, Inspection, Testing |
| 397 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B0031 | LINK, A/O GEARBOX REAR | 72-00-60 | Overhaul, Repair, Inspection, Testing |
| 398 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B0112 | LINK, A/O GEARBOX FRONT | 72-00-60 | Overhaul, Repair, Inspection, Testing |
| 399 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 6A4700 | LPC FAN BLADE | 72-31-11 | Overhaul, Repair, Inspection, Testing |
| 400 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 6A6521 | LPC FAN BLADE | 72-31-11 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------------|-------------|-------------|-------------------------------|----------|--|
| 401 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 6A7614 | LPC FAN BLADE | 72-31-11 | Overhaul, Repair, Inspection, Testing |
| 402 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 6A7654 | LPC FAN BLADE | 72-31-11 | Overhaul, Repair, Inspection, Testing |
| 403 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 6A7655 | LPC FAN BLADE | 72-31-11 | Overhaul, Repair, Inspection, Testing |
| 404 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A2510 | CONNEX. VIGV ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 405 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A2521 | CONNEX. STG3 ASSY,ACT.STBD | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 406 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A2523 | CONNEX. STG3 ASSY,ACT.PORT | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 407 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A2528 | CONNEX. STG4 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 408 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A2534 | CONNEX. STG5 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 409 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A2703 | CONNEC. STG6 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 410 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A2889 | BRACKET ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 411 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A2895 | BRACKET ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 412 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3535 | RING VIGV UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 413 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3537 | RING VIGV LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 414 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3539 | RING STG3 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 415 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3541 | RING STG3 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 416 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3543 | RING STG4 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 417 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3545 | RING STG4 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 418 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3547 | RING STG5 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 419 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3549 | RING STG5 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 420 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3551 | RING STG6 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 421 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3553 | RING STG6 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 422 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3681 | BRACKET ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 423 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3753 | RING STG3 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 424 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3982 | RING STG3 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 425 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3983 | RING STG4 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 426 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3984 | RING STG5 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 427 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A3987 | RING STG3 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 428 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A4333 | CONNEC. STG5 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 429 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A4340 | CONNEC. STG4 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 430 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7539 | CONNEC. STG5 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 431 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7540 | CONNEC. STG4 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 432 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7580 | RING VIGV UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 433 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7584 | RING VIGV LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 434 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7586 | CONNEC. VIGV ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 435 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7588 | RING STG3 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 436 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7590 | RING STG3 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 437 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7593 | CONNEC. STG3 ASSY,ACT.STBD | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 438 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7594 | CONNEC. STG3 ASSY,ACT.PORT | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 439 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7596 | RING STG4 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 440 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7599 | RING STG4 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 441 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7603 | CONNEC. STG4 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 442 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7605 | RING STG5 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 443 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7607 | RING STG5 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 444 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7611 | CONNEC. STG5 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 445 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7847 | BRIDGE VIGV ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 446 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7849 | RING VIGV UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 447 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7851 | RING VIGV LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 448 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7853 | BRIDGE STG3 ASSY STBD | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 449 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7855 | BRIDGE STG3 ASSY,PORT | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 450 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7858 | BRIDGE STG4 ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 451 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7860 | BRIDGE STG5 ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 452 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7861 | RING STG3 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 453 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7863 | RING STG3 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 454 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7865 | RING STG3 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 455 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7866 | BRIDGE STG4 ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 456 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7868 | RING STG4 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 457 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7869 | BRIDGE STG5 ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 458 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7888 | RING,ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 459 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7890 | RING STG4 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 460 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7893 | CONNEC. STG4 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 461 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7894 | RING STG5 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 462 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7896 | RING STG5 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 463 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7898 | CONNEC. STG5 ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 464 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7899 | RING VIGV UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 465 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7901 | RING VIGV LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 466 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7903 | RING STG3 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 467 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A7906 | RING STG3 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 468 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8075 | RING VIGV UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 469 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8077 | RING VIGV LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 470 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8079 | BRIDGE STG4 ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 471 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8080 | BRIDGE STG5 ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 472 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8086 | RING STG5 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 473 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8088 | RING STG5 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 474 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8097 | RING STG6 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 475 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8098 | RING STG6 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 476 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8115 | RING STG3 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 477 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8117 | RING STG3 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 478 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8119 | RING STG3 LOWER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 479 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8121 | RING STG4 UPPER ASSY, ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 480 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8123 | BRIDGE STG4 ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|-------------------------|----------|---------------------------------------|
| 481 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A8124 | BRIDGE STG5 ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 482 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A9106 | RING ASSY,VIGV-ACT.RING | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 483 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A9108 | RING ASSY,ACT.VIGV | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 484 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A9110 | RING ASSY STG3 UP(*) | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 485 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A9112 | RING ASSY STG3 LOWER | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 486 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A9114 | RING ASSY STG4 UP(*) | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 487 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A9116 | RING ASSY,ST.4,ACT.LO | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 488 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A9118 | RING ASSY STG.5 | 72-41-34 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|-------------------------------|----------|---------------------------------------|
| 489 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6A9120 | RING ASSY,ST.5,ACT.LO | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 490 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6B1068 | CONN, ASSY, VIGH ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 491 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6B1069 | CONN, ASSY, VIGH ACT. | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 492 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6B1084 | CONNECTOR,ASSY STG 5 | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 493 | 4/Jul/23 | Limited Engine | IAE - EM PN 2A4427 and PN 2A4416 | V2500 | 6B1085 | CONNECTOR,ASSY STG 5 | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 494 | 11/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A0084 | SUPPORT-ASSY, DIFFUSER, OUTER | 72-50-25 | Overhaul, Repair, Inspection, Testing |
| 495 | 11/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A0090 | DIFFUSER-ASSY, SEGMENT, OUTER | 72-50-25 | Overhaul, Repair, Inspection, Testing |
| 496 | 11/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A0958 | DIFFUSER-A/O, SEGMENT, OUTER | 72-50-25 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------------|-------------|-------------|----------------------------------|----------|--|
| 497 | 11/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A1791 | DIFFUSER-A/O, SEGMENT, OUTER | 72-50-25 | Overhaul, Repair, Inspection, Testing |
| 498 | 11/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A1907 | SUPPORT-ASSY, DIFFUSER, OUTER | 72-50-25 | Overhaul, Repair, Inspection, Testing |
| 499 | 11/Jul/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A2482 | DIFFUSER-A/O, SEGMENT, OUTER | 72-50-25 | Overhaul, Repair, Inspection, Testing |
| 500 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A2930 | HSG, ASSY STG 5 CONN | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 501 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4335 | HSG, ASSY STG 5 CONN | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 502 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A6540 | CONE, ASSY OF FRONT SUPPORT | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 503 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7577 | CONE, ASSY OF FRONT SUPPORT | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 504 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1430 | CONE, ASSY OF FRONT SUPPORT | 72-41-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------------|-------------|-------------|----------------------------|----------|--|
| 505 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B0053 | CASING, A/O GEARBOX | 72-60-21 | Overhaul, Repair, Inspection, Testing |
| 506 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B0054 | CASING, A/O GEARBOX | 72-60-21 | Overhaul, Repair, Inspection, Testing |
| 507 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B0055 | CASING | 72-60-21 | Overhaul, Repair, Inspection, Testing |
| 508 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B0057 | CASING, ASSY OF GEARBOX | 72-60-21 | Overhaul, Repair, Inspection, Testing |
| 509 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B0400 | CASING, A/O GBX | 72-60-21 | Overhaul, Repair, Inspection, Testing |
| 510 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B0402 | CASING, ASSY OF GEARBOX | 72-60-21 | Overhaul, Repair, Inspection, Testing |
| 511 | 9/Aug/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B0423 | CASING, ASSY OF GEARBOX | 72-60-21 | Overhaul, Repair, Inspection, Testing |
| 512 | 30/Aug/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 2A0250 | HPT CASE | 72-45-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|------------------|----------|---------------------------------------|
| 513 | 30/Aug/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 2A1591 | HPT CASE | 72-45-21 | Overhaul, Repair, Inspection, Testing |
| 514 | 30/Aug/23 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 2A1600 | HPT CASE | 72-45-21 | Overhaul, Repair, Inspection, Testing |
| 515 | 30/Aug/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1277M30P06 | BLADE-STG 1 | 72-21-01 | Overhaul, Repair, Inspection, Testing |
| 516 | 30/Aug/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1338M51P01 | BLADE-STG 1 | 72-21-01 | Overhaul, Repair, Inspection, Testing |
| 517 | 30/Aug/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1338M51P02 | BLADE-STG 1 | 72-21-01 | Overhaul, Repair, Inspection, Testing |
| 518 | 30/Aug/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1338M51P03 | BLADE-STG 1 | 72-21-01 | Overhaul, Repair, Inspection, Testing |
| 519 | 30/Aug/23 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1338M51P05 | BLADE-STG 1 | 72-21-01 | Overhaul, Repair, Inspection, Testing |
| 520 | 15/Sep/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5W2198 | LPC MID CASE | 72-32-83 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|----------------------------------|----------|--|
| 521 | 15/Sep/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 6A6548 | CASE, ASSY, STG.8, HPC COMPR. | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 522 | 15/Sep/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 6A7529 | CASE, ASSY, STG.8, HPC COMPR. | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 523 | 15/Sep/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 6A7578 | CASE, ASSY, STG.8, HPC COMPR. | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 524 | 15/Sep/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 6A7624 | CASE, ASSY, STG.8, HPC COMPR. | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 525 | 15/Sep/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 6B1432 | CASE, ASSY, STG.8, HPC COMPR. | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 526 | 3/Nov/23 | Limited Engine | GE - EM PN GEK112081 | CF34-10 | 2226M46P01 | RETAINER-STG.1 LPT SHROUD | 72-57-23 | Overhaul, Repair, Inspection, Testing |
| 527 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A0807 | CASE-ASSY, LPT | 72-50-21 | Overhaul, Repair, Inspection, Testing |
| 528 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A0990 | CASE-ASSY, LPT | 72-50-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------------|----------|--|
| 529 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A0991 | CASE-ASSY, LPT | 72-50-21 | Overhaul, Repair, Inspection, Testing |
| 530 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A1908 | CASE-ASSY, LPT | 72-50-21 | Overhaul, Repair, Inspection, Testing |
| 531 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A2183 | CASE-ASSY, LPT | 72-50-21 | Overhaul, Repair, Inspection, Testing |
| 532 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A2265 | CASE-ASSY, LPT | 72-50-21 | Overhaul, Repair, Inspection, Testing |
| 533 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A2447 | CASE-ASSY, LPT | 72-50-21 | Overhaul, Repair, Inspection, Testing |
| 534 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 3A2533 | CASE-A/O, LPT | 72-50-21 | Overhaul, Repair, Inspection, Testing |
| 535 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A0433 | VANE, A/O STG 2.0 LPC | 72-32-83 | Overhaul, Repair, Inspection, Testing |
| 536 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A0436 | VANE, ASSY STG 1.5 LPC | 72-32-83 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|-------------------------------|----------|--|
| 537 | 3/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A1412 | STATOR, A/O STG 2.3 | 72-32-83 | Overhaul, Repair, Inspection, Testing |
| 538 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B2905-01 | COVER, VALVE, COLD START | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 539 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B4991-01 | COVER,BLEED AIR,REAR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 540 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B5589-01 | ADAPTER,ELBO,TUBE TO BOSS | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 541 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B5662-01 | COVER,AIR BLEED,HIGH PRESS | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 542 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B6048-01 | ADAPTER, 1 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 543 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1445-01 | ADAPTER ASSY, TUBE TO BOSS | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 544 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1446-01 | ADAPTER, STRAIGHT | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|-----------------------------|----------|---------------------------------------|
| 545 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1485-01 | PLUG, MACHINE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 546 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1503-01 | ADAPTER, STRAIGHT, 2 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 547 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1698-01 | PLUG, BLEEDER, TUBE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 548 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1979-01 | ADAPTER, STRAIGHT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 549 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2244-01 | COVER, LP BLEED, PAD | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 550 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2245-01 | RETAINER, TUBE, CABIN AIR | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 551 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2683-01 | ADAPTER, STRAIGHT, TWO HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 552 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3641-01 | COVER, O/S CONTR. LINKAGE | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|-----------------------------|----------|---------------------------------------|
| 553 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3689-01 | PLUG | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 554 | 3/Nov/23 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4201-01 | COVER-BLANKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 555 | 13/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A1422 | BRACKET, A/O T/MOUNT NO. 2 | 71-21-11 | Overhaul, Repair, Inspection, Testing |
| 556 | 13/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A1423 | BRACKET, A/O T/MNT NO. 10 | 71-21-11 | Overhaul, Repair, Inspection, Testing |
| 557 | 13/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A1431 | BRACKET, A/O T/MOUNT NO. 2 | 71-21-11 | Overhaul, Repair, Inspection, Testing |
| 558 | 13/Nov/23 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A1432 | BRACKET, A/O T/MOUNT NO. 10 | 71-21-11 | Overhaul, Repair, Inspection, Testing |
| 559 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9392 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 560 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9882 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|----------------------|----------|--|
| 561 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9882-001 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 562 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B2772 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 563 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B2772-002 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 564 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6182 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 565 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6182-001 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 566 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6192 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 567 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6382-01 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 568 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6382-021 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|----------------------|----------|--|
| 569 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6482-01 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 570 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6482-021 | LP COMP.STTR Y STG 2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 571 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7672-001 | VANE,LPC,STG2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 572 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7672-01 | VANE,LPC,STG2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 573 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7772-001 | VANE,LPC,STG2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 574 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7772-01 | VANE,LPC,STG2 | 72-31-26 | Overhaul, Repair, Inspection, Testing |
| 575 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9393 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 576 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9473 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|----------------------|----------|--|
| 577 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9783 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 578 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9783-001 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 579 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9883 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 580 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9883-001 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 581 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B2473 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 582 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B2473-002 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 583 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B2773 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 584 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B2773-002 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|----------------------|----------|--|
| 585 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6183 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 586 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6183-001 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 587 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6193 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 588 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6273 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 589 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6283 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 590 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6283-001 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 591 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6383-01 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 592 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6383-021 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|----------------------|----------|--|
| 593 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6483-01 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 594 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6483-021 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 595 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7283-021 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 596 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7293-021 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 597 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7673-001 | VANE,LPC,STG3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 598 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7673-01 | VANE,LPC,STG3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 599 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7773-001 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |
| 600 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7773-01 | LP COMP.STTR Y STG 3 | 72-31-27 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|----------------------|----------|--|
| 601 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9394 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 602 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9394-001 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 603 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9884 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 604 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1A9884-001 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 605 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B2774 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 606 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B2774-002 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 607 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6184 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 608 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6184-001 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|---------------------|----------------------------|----------|--|
| 609 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B6394-021 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 610 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7284-021 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 611 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7674-001 | VANE,LPC,STG4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 612 | 13/Nov/23 | Limited Engine | PW - EM PN 1A6231 | PW2000 | 1B7674-01 | LP COMP.STTR Y STG 4 | 72-31-28 | Overhaul, Repair, Inspection, Testing |
| 613 | 12/Jan/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M68G01 | CASING-BOOSTER STATOR | 72-25-03 | Overhaul, Repair, Inspection, Testing |
| 614 | 12/Jan/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M68G04 | FAN STATOR CASE STG 2-4 | 72-25-03 | Overhaul, Repair, Inspection, Testing |
| 615 | 12/Jan/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M68G04SB 084 | FAN CASE STATOR STG 2-4 | 72-25-03 | Overhaul, Repair, Inspection, Testing |
| 616 | 12/Jan/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M68G05 | FAN STATOR CASE STG 2-4 | 72-25-03 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------------|-------------|---------------------|---------------------------------|----------|--|
| 617 | 12/Jan/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M68G05SB 084 | FAN STTR CASE STG2-4 | 72-25-03 | Overhaul, Repair, Inspection, Testing |
| 618 | 12/Jan/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M68G06 | BOOSTER CASE STG.2-4 | 72-25-03 | Overhaul, Repair, Inspection, Testing |
| 619 | 12/Jan/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9385M68G10 | BOOSTER CASE STG.2-4 | 72-25-03 | Overhaul, Repair, Inspection, Testing |
| 620 | 12/Jan/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1070 | CONNECTOR,ASSY STG 3 | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 621 | 12/Jan/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1071 | CONNECTOR,ASSY STG 3 | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 622 | 12/Jan/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1081 | CONNECTOR,ASSY STG 4 | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 623 | 12/Jan/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6B1082 | CONNECTOR,ASSY STG 4 | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 624 | 12/Jan/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5A1184 | HOUSING, A/O CENTRE BRG, PTO | 72-32-05 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------------|-------------|-------------|---------------------------------|----------|--|
| 625 | 12/Jan/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5A1433 | HOUSING, A/O CENTRE BRG, PTO | 72-32-05 | Overhaul, Repair, Inspection, Testing |
| 626 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2070M12G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 627 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2070M13G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 628 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2070M14G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 629 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2070M15G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 630 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2070M16G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 631 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M79G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 632 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M80G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------|----------|--|
| 633 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M81G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 634 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M82G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 635 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M83G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 636 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M84G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 637 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M85G01 | FLOW SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 638 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M03G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 639 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M04G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 640 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M05G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------|----------|--|
| 641 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M06G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 642 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M07G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 643 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M08G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 644 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M09G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 645 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M10G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 646 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M11G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 647 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M12G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 648 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M13G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|---|-------------|-------------|----------------------------|----------|--|
| 649 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2601M14G01 | FLOWPATH SEGMENT | 72-23-07 | Overhaul, Repair, Inspection, Testing |
| 650 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 45P1041 | Splitter | 72-23-09 | Overhaul, Repair, Inspection, Testing |
| 651 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112031 AND GEK112031-1 | CF34-8E | 4114T06P01 | FAN BLADE RETAINING PIN | 72-21-12 | Overhaul, Repair, Inspection, Testing |
| 652 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112031 AND GEK112031-1 | CF34-8E | 4114T06P02 | FAN BLADE RETAINING PIN | 72-21-12 | Overhaul, Repair, Inspection, Testing |
| 653 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112031 AND GEK112031-1 | CF34-8E | 4114T06P03 | FAN BLADE RETAINING PIN | 72-21-12 | Overhaul, Repair, Inspection, Testing |
| 654 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M87G01 | LPT AIR DUCT | 72-57-14 | Overhaul, Repair, Inspection, Testing |
| 655 | 12/Jan/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M88G01 | LPT TEE AIR DUCT | 72-57-14 | Overhaul, Repair, Inspection, Testing |
| 656 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30A1307 | FLANGE | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|----------------------|----------|---------------------------------------|
| 657 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30A1321 | PLUG-BLANKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 658 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30A2152 | PLUG-A/O,BLANKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 659 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B3501-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 660 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B3877-01 | ADAPTER, FLANGED TEE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 661 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B4030-01 | ADAPTER, 1 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 662 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B5055-01 | ADAPTER, FLANGED TEE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 663 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B5322-01 | ADAPTER, FLANGED TEE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 664 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30B5866-01 | ADAPTER, DRAIN VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|----------------------|----------|--|
| 665 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C1570-01 | COVER, VALVE COLD ST | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 666 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C1650-01 | TUBE, SUPP., FUEL N | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 667 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C1652-01 | COVER, TUBE, SUPPORT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 668 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C1919-01 | ADAPTER, STRAIGHT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 669 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C1930-01 | ADAPTER, STRAIGHT, 2 | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 670 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C3442-01 | PLUG, PO AIR, EEC TO | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 671 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C3669-01 | TEE, ADAPTER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 672 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C4005-01 | COVER ASSY, P2.8 / P | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--------------------------------|-------------|-------------|----------------------|----------|--|
| 673 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C4141-01 | PLUG LOW PRESSURE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 674 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C4421-01 | TUBE, SUPP., FUEL NO | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 675 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C4576-01 | COVER ASSY, P2.8 /P3 | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 676 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C4583-01 | PLUG, BLANKING, CONN | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 677 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C4719-01 | COVER ASSY, P2.8/ P3 | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 678 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C4721-01 | COVER, P2.8/P3 AIR, | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 679 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30C4987-01 | TEE, ADAPTER | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 680 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 30P0318-01 | PLUG LP SHAFT | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|--|----------|---------------------------------------|
| 681 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1422-01 | PLUG, LC SHAFT, REAR COVER, O/S CONTR. LINKAGE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 682 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1486-01 | OVER, O/S CONTR. LINKAGE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 683 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B1975-01 | ADAPTER, DRAIN VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 684 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2205-01 | ADAPTER, STRAIGHT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 685 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2342-01 | ADAPTER, TUBE TO BOSS | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 686 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2343-01 | PLUG, BLANKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 687 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2344-01 | ADAPTER, STRAIGHT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 688 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2353-01 | VER, O/P ADJUSTING VAL | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|-------------------------|----------|---------------------------------------|
| 689 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2722-01 | ADAPTER, FLANGE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 690 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2880-01 | ATE, BLANKING, P2.8 BOS | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 691 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B2903-01 | COVER, BLEED VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 692 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3141-01 | ADAPTER, FLANGED TEE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 693 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3230-01 | OVER ASSY, BLEED VALV | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 694 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3349-01 | COVER, PLATE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 695 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3855-01 | ACKET, MOUNT, FILLER NE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 696 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3878-01 | ATE, BLANKING, P2.8 BOS | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|--------------------------|----------|---------------------------------------|
| 697 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3977-01 | COVER, PLAIN, FLANGED | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 698 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B3978-01 | PLATE, BLANKING, 2 HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 699 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4404-01 | ADAPTER, FLANGED TEE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 700 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4487-01 | COVER, PACKING | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 701 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4831-01 | ADAPTER, STRAIGHT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 702 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4888-01 | ADAPTER, TWO HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 703 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B4917-01 | ADAPTER, TWO HOLE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 704 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B5326-01 | COVER, VALVE, COLD START | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------|-------------|-------------|---------------------------|----------|---------------------------------------|
| 705 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | 31B6278-01 | ADAPTER, STRAIGHT | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 706 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | MS9902-03 | PLUG | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 707 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | MS9902-04 | PLUG-MACHINE THD | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 708 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | ST3317-01 | ADAPTER, DRAIN VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 709 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | ST3342-01 | PLUG, MACHINE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 710 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | ST3661-01 | OVER, O/S CONTR. LINKAGE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 711 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | ST3679-01 | PLUG, GEARSHAFT, OIL PUMP | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 712 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | ST6111-01 | ADAPTER, DRAIN VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|------------------------|----------|---------------------------------------|
| 713 | 12/Jan/24 | Limited Engine | PWC - CIR MANUAL PN 30B4133 | PW300 | ST6126-01 | ADAPTER, DRAIN VALVE | 72-09-94 | Overhaul, Repair, Inspection, Testing |
| 714 | 12/Jan/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A2925 | HSG, ASSY STG 3 CONN | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 715 | 12/Jan/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3988 | HSG, ASSY STG 3 CONN | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 716 | 27/Feb/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A2927 | HSG, ASSY STG 4 CONN | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 717 | 27/Feb/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4810 | HSG, ASSY STG 4 CONN | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 718 | 27/Feb/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4343 | HOUSING, ASSY | 72-41-34 | Overhaul, Repair, Inspection, Testing |
| 719 | 27/Feb/24 | Limited Engine | GE- EM PN GEK105091 AND GEK9250 | CF34-8C | 4118T70P01 | LINER OUTER-TRANSITION | 72-57-03 | Overhaul, Repair, Inspection, Testing |
| 720 | 27/Feb/24 | Limited Engine | GE- EM PN GEK105091 AND GEK9250 | CF34-8C | 4118T70P02 | LINER OUTER-TRANSITION | 72-57-03 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|------------------------|----------|---------------------------------------|
| 721 | 27/Feb/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5R0029 | VANE,LPC,STG2.5 | 72-32-76 | Overhaul, Repair, Inspection, Testing |
| 722 | 27/Feb/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5R0097 | STATOR,A/O STG 2.5 LPC | 72-32-76 | Overhaul, Repair, Inspection, Testing |
| 723 | 27/Feb/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5R0168 | STATOR,A/O STG 2.5 LPC | 72-32-76 | Overhaul, Repair, Inspection, Testing |
| 724 | 27/Feb/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5R0189 | STATOR,A/O STG 2.5 LPC | 72-32-76 | Overhaul, Repair, Inspection, Testing |
| 725 | 27/Feb/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5R0195 | STATOR,A/O STG 2.5 LPC | 72-32-76 | Overhaul, Repair, Inspection, Testing |
| 726 | 27/Feb/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5R6088 | VANE,LPC,STG2.5 | 72-32-76 | Overhaul, Repair, Inspection, Testing |
| 727 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M72G05 | MANIFOLD-AIR | 72-57-15 | Overhaul, Repair, Inspection, Testing |
| 728 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M72G06 | MANIFOLD-AIR | 72-57-15 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------|----------|--|
| 729 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M72G07 | MANIFOLD-AIR | 72-57-15 | Overhaul, Repair, Inspection, Testing |
| 730 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M72G08 | MANIFOLD-AIR | 72-57-15 | Overhaul, Repair, Inspection, Testing |
| 731 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2227M63G01 | MANIFOLD-AIR | 72-57-15 | Overhaul, Repair, Inspection, Testing |
| 732 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2227M63G02 | MANIFOLD-AIR | 72-57-15 | Overhaul, Repair, Inspection, Testing |
| 733 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2227M63G03 | MANIFOLD-AIR | 72-57-15 | Overhaul, Repair, Inspection, Testing |
| 734 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2227M63G04 | MANIFOLD-AIR | 72-57-15 | Overhaul, Repair, Inspection, Testing |
| 735 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2070M37G03 | FAIRING STRUT | 72-23-23 | Overhaul, Repair, Inspection, Testing |
| 736 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2070M37G04 | FAIRING-STRUT | 72-23-23 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------|----------|--|
| 737 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M56P01 | FAIRING-STRUT | 72-23-23 | Overhaul, Repair, Inspection, Testing |
| 738 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M56P02 | FAIRING-STRUT | 72-23-23 | Overhaul, Repair, Inspection, Testing |
| 739 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M93P01 | FAIRING-STRUT | 72-23-23 | Overhaul, Repair, Inspection, Testing |
| 740 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M93P02 | FAIRING-STRUT | 72-23-23 | Overhaul, Repair, Inspection, Testing |
| 741 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2131M65G01 | FAIRING-STRUT | 72-23-23 | Overhaul, Repair, Inspection, Testing |
| 742 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2072M71G01 | SUPPORT | 72-23-23 | Overhaul, Repair, Inspection, Testing |
| 743 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2070M23G01 | ACT RING ASSY | 72-23-14 | Overhaul, Repair, Inspection, Testing |
| 744 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2070M44G01 | CASE REAR | 72-32-01 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|--------------|----------------------|----------|--|
| 745 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2131M99G01 | SUPPORT | 72-23-23 | Overhaul, Repair, Inspection, Testing |
| 746 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 9303M42P02 | COUPLING | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 747 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | AS1895-1-225 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 748 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | AS1895-1-300 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 749 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | AS1895-4-125 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 750 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | AS1895-4-150 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 751 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | AS1895-4-200 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 752 | 27/Feb/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | AS1895-4-300 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|--------------|----------------------|----------|--|
| 753 | 27/Feb/24 | Limited Engine | GE - EM PN GEK105091 | CF34-8C | 9303M42P02 | COUPLING | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 754 | 27/Feb/24 | Limited Engine | GE - EM PN GEK105091 | CF34-8C | AS1895-1-225 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 755 | 27/Feb/24 | Limited Engine | GE - EM PN GEK105091 | CF34-8C | AS1895-4-125 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 756 | 27/Feb/24 | Limited Engine | GE - EM PN GEK105091 | CF34-8C | AS1895-4-175 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 757 | 27/Feb/24 | Limited Engine | GE - EM PN GEK105091 | CF34-8C | AS1895-4-200 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 758 | 27/Feb/24 | Limited Engine | GE - EM PN GEK105091 | CF34-8C | AS1895-4-250 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 759 | 27/Feb/24 | Limited Engine | GE - EM PN GEK105091 | CF34-8C | AS1895-4-300 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 760 | 27/Feb/24 | Limited Engine | GE- EM-GEK112031 | CF34-8E | 9303M42P02 | COUPLING | 72-09-01 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|---|-------------|--------------|----------------------|----------|--|
| 761 | 27/Feb/24 | Limited Engine | GE- EM-GEK112031 | CF34-8E | AS1895-1-225 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 762 | 27/Feb/24 | Limited Engine | GE- EM-GEK112031 | CF34-8E | AS1895-1-300 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 763 | 27/Feb/24 | Limited Engine | GE- EM-GEK112031 | CF34-8E | AS1895-4-125 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 764 | 27/Feb/24 | Limited Engine | GE- EM-GEK112031 | CF34-8E | AS1895-4-200 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 765 | 27/Feb/24 | Limited Engine | GE- EM-GEK112031 | CF34-8E | AS1895-4-250 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 766 | 27/Feb/24 | Limited Engine | GE- EM-GEK112031 | CF34-8E | AS1895-4-300 | COUPLING, V-RETAINER | 72-09-01 | Overhaul, Repair, Inspection, Testing |
| 767 | 27/Feb/24 | Limited Engine | GE - EM PN GEK105091 AND GEK105091-1 | CF34-8C | 4114T15P02 | FAN BLADE | 72-21-13 | Overhaul, Repair, Inspection, Testing |
| 768 | 27/Feb/24 | Limited Engine | GE - EM PN GEK105091 AND GEK105091-1 | CF34-8C | 4114T31G01 | FAN BLADE | 72-21-13 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--|-------------|-------------|----------------------------|----------|--|
| 769 | 27/Feb/24 | Limited Engine | GE- EM PN GEK105091 AND GEK105091-1 | CF34-8C | 4114T06P01 | FAN BLADE RETAINING PIN | 72-21-12 | Overhaul, Repair, Inspection, Testing |
| 770 | 27/Feb/24 | Limited Engine | GE- EM PN GEK105091 AND GEK105091-1 | CF34-8C | 4114T06P02 | FAN BLADE RETAINING PIN | 72-21-12 | Overhaul, Repair, Inspection, Testing |
| 771 | 27/Feb/24 | Limited Engine | GE- EM PN GEK105091 AND GEK105091-1 | CF34-8C | 4114T06P03 | FAN BLADE RETAINING PIN | 72-21-12 | Overhaul, Repair, Inspection, Testing |
| 772 | 27/Feb/24 | Limited Engine | GE- EM PN GEK112031 AND GEK9250 | CF34-8E | 4118T70P01 | LINER OUTER- TRANSITION | 72-57-03 | Overhaul, Repair, Inspection, Testing |
| 773 | 27/Feb/24 | Limited Engine | GE- EM PN GEK112031 AND GEK9250 | CF34-8E | 4118T70P02 | LINER OUTER- TRANSITION | 72-57-03 | Overhaul, Repair, Inspection, Testing |
| 774 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112031 AND GEK112031-1 | CF34-8E | 1822M28G03 | CASE-COMP | 72-32-06 | Overhaul, Repair, Inspection, Testing |
| 775 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112031 AND GEK112031-1 | CF34-8E | 1822M28G04 | CASE-COMP | 72-32-06 | Overhaul, Repair, Inspection, Testing |
| 776 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112031 AND GEK112031-1 | CF34-8E | 1822M28G05 | CASE-COMP | 72-32-06 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|--|-------------|-------------|-------------------------------------|----------|--|
| 777 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112031 AND GEK112031-1 | CF34-8E | 1822M28P01 | COMP C UPP | 72-32-06 | Overhaul, Repair, Inspection, Testing |
| 778 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112031 AND GEK112031-1 | CF34-8E | 1822M28P02 | COMP LOW | 72-32-06 | Overhaul, Repair, Inspection, Testing |
| 779 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112031 AND GEK112031-1 | CF34-8E | 4923T98G03 | CASE-COMP | 72-32-06 | Overhaul, Repair, Inspection, Testing |
| 780 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A0211 | RETAINER, RING ASSY, BLADE, REAR | 72-31-12 | Overhaul, Repair, Inspection, Testing |
| 781 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A0897 | RETAINER, RING ASSY, BLADE, REAR | 72-31-12 | Overhaul, Repair, Inspection, Testing |
| 782 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 308M32G01 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 783 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G03 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 784 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G04 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------|----------|--|
| 785 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G05 | LINK, SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 786 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G06 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 787 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G07 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 788 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G08 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 789 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G11 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 790 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G12 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 791 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G14 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 792 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G17 | LINK SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-----------------------------|----------|--|
| 793 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G19 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 794 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G20 | LINK | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 795 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G21 | LINK | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 796 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G22 | LINK-SUPPORT, RIGHT SIDE | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 797 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G23 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 798 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G24 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 799 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G27 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 800 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1308M32G34 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|---------------------------|----------|--|
| 801 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1310M25G03 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 802 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1473M58G01 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 803 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1473M58P01 | HOUSING, BEARING (SPD) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 804 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1578M30G02 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 805 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1578M30G08 | LINK, SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 806 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1578M30G12 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 807 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1578M30G14 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 808 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1578M30G18 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------|----------|--|
| 809 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1578M30G21 | LINK SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 810 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1578M30G22 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 811 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1578M30G28 | LINK SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 812 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1578M30G36 | LINK,SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 813 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1578M30G49 | LINK-SUPPORT | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 814 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1854M36P01 | SPACER-STG 1 | 72-21-11 | Overhaul, Repair, Inspection, Testing |
| 815 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9326M60P01 | SPACER,STG 1 | 72-21-11 | Overhaul, Repair, Inspection, Testing |
| 816 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2230M39G01 | SHAFT RDS | 72-62-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-----------------------------|----------|---------------------------------------|
| 817 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A6024 | RACE, ASSY OUTER TUBE MOUNT | 71-21-11 | Overhaul, Repair, Inspection, Testing |
| 818 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M91P02 | BOLT, SLABBED | 72-55-06 | Overhaul, Repair, Inspection, Testing |
| 819 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M91P03 | BOLT, SLABBED | 72-55-06 | Overhaul, Repair, Inspection, Testing |
| 820 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M92P02 | BOLT DOUBLE HEX | 72-55-06 | Overhaul, Repair, Inspection, Testing |
| 821 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M93P02 | BOLT | 72-55-06 | Overhaul, Repair, Inspection, Testing |
| 822 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2227M70P01 | BOLT | 72-55-06 | Overhaul, Repair, Inspection, Testing |
| 823 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2228M14P01 | BOLT, DOUBLE HEX | 72-55-06 | Overhaul, Repair, Inspection, Testing |
| 824 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2030M21G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 825 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2030M30G01 | TUBE-FUEL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 826 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2030M32G01 | TUBE-OIL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 827 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2030M35G01 | TUBE-OIL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 828 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2030M37G01 | TUBE-OIL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 829 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2030M39G01 | TUBE-OIL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 830 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2035M75G01 | TUBE-OIL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 831 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2053M12P01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 832 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2053M29G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-----------------------|----------|--|
| 833 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2058M87G01 | TUBE | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 834 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2058M90G01 | MANIFOLD-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 835 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2059M27G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 836 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2098M46P01 | TUBE-FUEL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 837 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2098M53G01 | MANIFOLD-FUEL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 838 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2170M10G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 839 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2170M38G01 | TUBE-FUEL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 840 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2176M26G01 | TUBE-OIL (SCAVENGE) | 72-09-04 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-----------------------|----------|--|
| 841 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2176M32G01 | TUBE-OIL (VENT) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 842 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2177M12G01 | MANIFOLD-FUEL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 843 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2177M35G01 | MANIFOLD-OIL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 844 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2191M89P01 | TUBE-OIL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 845 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2226M77G01 | TUBE-A/O OIL DRAIN | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 846 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2278M69G01 | MANIFOLD-FUEL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 847 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2284M27G01 | TUBE-OIL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 848 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2284M48G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-----------------------|----------|--|
| 849 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2284M49G01 | DUCT-LPTACC | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 850 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2284M77G01 | MANIFOLD-FUEL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 851 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2284M80G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 852 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2284M81G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 853 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2284M82G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 854 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2284M83G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 855 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2290M97G01 | TUBE-OIL (SCAVENGE) | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 856 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2298M26G01 | TUBE-FUEL (DRAIN) | 72-09-04 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------------|-------------|-------------|----------------------------|----------|--|
| 857 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2367M92G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 858 | 11/Jun/24 | Limited Engine | GE - EM PN GEK112081 | CF34-10E | 2369M19G01 | TUBE-AIR | 72-09-04 | Overhaul, Repair, Inspection, Testing |
| 859 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A0460 | FAIRING, SPLITTER FRONT | 72-32-93 | Overhaul, Repair, Inspection, Testing |
| 860 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3651 | RING,ST.7-R/PATH | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 861 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4101 | RING ST.7 PATH HP- COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 862 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4161 | RING,ST.7-R/PATH | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 863 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A5992 | RING ST.7 PATH HP- COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 864 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A5995 | RING ST.7 PATH HP- COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------------------|-------------|-------------|------------------------|----------|---------------------------------------|
| 865 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7623 | RING ST.7 PATH HP-COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 866 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7626 | RING ST.7 PATH HP-COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 867 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A3652 | RING, ST.8 R/PATH | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 868 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4102 | RING ST.8 PATH HP-COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 869 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A4162 | RING ST.8 PATH HP-COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 870 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A5993 | RING ST.8 PATH HP-COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 871 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A5996 | RING ST.8 PATH HP-COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 872 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7625 | RING ST.8 PATH HP-COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------------|-------------|-------------|----------------------------|----------|--|
| 873 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 6A7627 | RING ST.8 PATH HP- COMP | 72-41-21 | Overhaul, Repair, Inspection, Testing |
| 874 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M79G03 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 875 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M79G04 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 876 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M79G05 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 877 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M79G06 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 878 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M79G07 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 879 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M79G08 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 880 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M79G09 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|----------------------------|----------|--|
| 881 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M79G10 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 882 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2459M04G01 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 883 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B7049 | .CASING,A/O,AIR PORT | 72-60-31 | Overhaul, Repair, Inspection, Testing |
| 884 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B7153 | CASING,A/O DEOILER | 72-60-31 | Overhaul, Repair, Inspection, Testing |
| 885 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B7262 | CASING, A/O DEOILER | 72-60-31 | Overhaul, Repair, Inspection, Testing |
| 886 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 4B7361 | CASING DEOILER | 72-60-31 | Overhaul, Repair, Inspection, Testing |
| 887 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4416 | V2500 | 4B7049 | CASING,A/O,AIR PORT | 72-60-31 | Overhaul, Repair, Inspection, Testing |
| 888 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4416 | V2500 | 4B7291 | CASING, A/O DEOILER | 72-60-31 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-----------------------------------|-------------|---------------|------------------|----------|--|
| 889 | 11/Jun/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-252-305-0 | SHIM-FAN BLADE | 72-21-22 | Overhaul, Repair, Inspection, Testing |
| 890 | 11/Jun/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-252-306-0 | SHIM-FAN BLADE | 72-21-22 | Overhaul, Repair, Inspection, Testing |
| 891 | 11/Jun/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7 | 340-252-307-0 | SHIM-FAN BLADE | 72-21-22 | Overhaul, Repair, Inspection, Testing |
| 892 | 11/Jun/24 | Limited Engine | GE- EM-GEK112031 | CF34-8E | 4138T62G04 | ENG AFT MT | 71-20-01 | Overhaul, Repair, Inspection, Testing |
| 893 | 11/Jun/24 | Limited Engine | PW - EM PN5319156 and PN585005 | PW1100G | 30G2976-01 | CASE HPT | 72-51-11 | Overhaul, Repair, Inspection, Testing |
| 894 | 11/Jun/24 | Limited Engine | PW - EM PN5319156 and PN585005 | PW1100G | 30G4127-01 | CASE HPT, ASSY | 72-51-11 | Overhaul, Repair, Inspection, Testing |
| 895 | 11/Jun/24 | Limited Engine | PW - EM PN5319156 and PN585005 | PW1100G | 30G4184-01 | CASE HPT, ASSY | 72-51-11 | Overhaul, Repair, Inspection, Testing |
| 896 | 11/Jun/24 | Limited Engine | PW - EM PN5319156 and PN585005 | PW1100G | 30G4185-01 | CASE HPT, ASSY | 72-51-11 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 897 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112031 | CF34-8E | 3066T16G04 | CASE-FAN BLD | 72-23-01 | Overhaul, Repair, Inspection, Testing |
| 898 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112031 | CF34-8E | 3066T16G05 | CASE-FAN BLD | 72-23-01 | Overhaul, Repair, Inspection, Testing |
| 899 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112031 | CF34-8E | 3066T16G07 | CASE-FAN BLD | 72-23-01 | Overhaul, Repair, Inspection, Testing |
| 900 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 45P1082 | BOOSTER IGV ASSY | 72-21-09 | Overhaul, Repair, Inspection, Testing |
| 901 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 45P1065 | STAGE 2 VANE ASSY | 72-21-09 | Overhaul, Repair, Inspection, Testing |
| 902 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 45P1169 | STAGE 3 VANE ASSY | 72-21-09 | Overhaul, Repair, Inspection, Testing |
| 903 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 45P1075 | STAGE 4 VANE ASSY | 72-21-09 | Overhaul, Repair, Inspection, Testing |
| 904 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2050M56P01 | FAN BLADE REAINER | 72-21-01 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-------------------|----------|--|
| 905 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2050M56P02 | FAN BLADE REAINER | 72-21-01 | Overhaul, Repair, Inspection, Testing |
| 906 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2050M56P04 | FAN BLADE REAINER | 72-21-01 | Overhaul, Repair, Inspection, Testing |
| 907 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2489M01P01 | FAN BLADE REAINER | 72-21-01 | Overhaul, Repair, Inspection, Testing |
| 908 | 11/Jun/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 4115T35P01 | RING-AXS-B | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 909 | 11/Jun/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 4115T35P02 | RING-AXS-B | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 910 | 11/Jun/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 4115T36P01 | RING-AXS-D | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 911 | 11/Jun/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 4115T36P02 | RING-AXS-D | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 912 | 11/Jun/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 4115T37P01 | RING-AXS-G | 72-64-19 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------|----------|--|
| 913 | 11/Jun/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 4115T37P02 | RING-AXS-F | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 914 | 11/Jun/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 4115T38P01 | RING-AXS E | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 915 | 11/Jun/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 4115T38P02 | RING-AXS E | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 916 | 11/Jun/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 4115T39P01 | RING-AXS-C | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 917 | 11/Jun/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 4115T39P02 | RING-AXS-E/G | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 918 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2072M88G01 | FAIRING, STRUT | 72-23-23 | Overhaul, Repair, Inspection, Testing |
| 919 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2072M88G02 | FAIRING, STRUT | 72-23-23 | Overhaul, Repair, Inspection, Testing |
| 920 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2072M88G03 | FAIRING, STRUT | 72-23-23 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|--------------------------|----------|--|
| 921 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2050M62P01 | SPACER FAN BLADE | 72-21-03 | Overhaul, Repair, Inspection, Testing |
| 922 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2050M62P02 | SPACER FAN BLADE | 72-21-03 | Overhaul, Repair, Inspection, Testing |
| 923 | 11/Jun/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2050M62P03 | SPACER FAN BLADE | 72-21-03 | Overhaul, Repair, Inspection, Testing |
| 924 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1292M13G03 | PLATFORM ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 925 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1292M13G04 | PLATFORM ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 926 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1292M13G05 | PLATFORM ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 927 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1292M13G06 | PLATFORM ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 928 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1301M28G04 | PLATFORM-ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|---------------------------|----------|---------------------------------------|
| 929 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1301M28G05 | PLATFORM-ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 930 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1301M28G06 | PLATFORM-ENGINE MOUNT (*) | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 931 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1301M28G07 | PLATFORM-ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 932 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1301M28G08 | PLATFORM-ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 933 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1459M70G06 | PLATFORM ASSY ENG. MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 934 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1459M70P01 | PLATFORM ENG. MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 935 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1806M79G01 | YOKE ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 936 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1806M79G02 | YOKE ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|--------------------------|----------|---------------------------------------|
| 937 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1806M80G01 | PLATFORM, FWD ENG. MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 938 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1806M87G01 | PLATFORM-ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 939 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1806M88G01 | PLATFORM ASSY ENG. MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 940 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1846M24G02 | PLATFORM ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 941 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1846M24G03 | PLATFORM ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 942 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1846M24G04 | PLATFORM ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 943 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1846M24G05 | PLATFORM ASSY ENG. MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 944 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1846M24G06 | PLATFORM ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|----------------------------|----------|---------------------------------------|
| 945 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1846M24G07 | PLATFORM ASSY ENG. MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 946 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9383M43G08 | YOKE-ENGINE MOUNT ASSY | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 947 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9383M43G10 | YOKE-ENGINE MOUNT ASSY | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 948 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9383M43G11 | YOKE-ENGINE MOUNT ASSY (*) | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 949 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9383M43G13 | YOKE-ENGINE MOUNT ASSY | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 950 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 9383M43G14 | YOKE-ENGINE MOUNT ASSY | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 951 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1806M80P01 | PLATFORM-ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |
| 952 | 11/Jun/24 | Limited Engine | GE - EM PN GEK 92451 | CF6-80C2 | 1806M87P01 | PLATFORM ENGINE MOUNT | 71-21-01 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|--------------------------|----------|--|
| 953 | 11/Jun/24 | Limited Engine | IAE - CMM PN 2A4412 | V2500 | 3A1745 | SUPPORT ASSY | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 954 | 11/Jun/24 | Limited Engine | IAE - CMM PN 2A4412 | V2500 | 3A1749 | SUPPORT ASSY | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 955 | 11/Jun/24 | Limited Engine | IAE - CMM PN 2A4412 | V2500 | 3A1752 | SUPPORT ASSY | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 956 | 11/Jun/24 | Limited Engine | IAE - CMM PN 2A4412 | V2500 | 3A1755 | SUPPORT ASSY | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 957 | 11/Jun/24 | Limited Engine | IAE - CMM PN 2A4412 | V2500 | 3A1759 | SUPPORT ASSY | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 958 | 11/Jun/24 | Limited Engine | IAE - CMM PN 2A4412 | V2500 | 3A1762 | SUPPORT ASSY | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 959 | 11/Jun/24 | Limited Engine | IAE - CMM PN 2A4412 | V2500 | 3A2320 | SUPPORT ASSY | 75-24-49 | Overhaul, Repair, Inspection, Testing |
| 960 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1845M90G04 | DAMPER STATIONARY LPT | 72-54-22 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|-----------------------------|----------|--|
| 961 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A0015 | CONE,ASSY INLET | 72-38-11 | Overhaul, Repair, Inspection, Testing |
| 962 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A1452 | CONE,ASSY INLET | 72-38-11 | Overhaul, Repair, Inspection, Testing |
| 963 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 | V2500 | 5A1733 | CONE,ASSY INLET | 72-38-11 | Overhaul, Repair, Inspection, Testing |
| 964 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1688M99P08 | BUSHING GRBX LINK FAN FR | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 965 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1768M25P06 | BUSHING | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 966 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1770M21G07 | LINK ASSY RIGHT SIDE | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 967 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1770M21G09 | LINK ASSY RIGHT SIDE | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 968 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1770M22G03 | LINK LEFT SIDE | 72-64-08 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------------|----------|--|
| 969 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1995M10P01 | AXE GRBX AXL MT | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 970 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1995M11P01 | AXE FAN FR AXL MT | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 971 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1995M13P01 | AXE LINK VERTICAL | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 972 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1995M14P01 | AXE LINK VERTICAL | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 973 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2205M44G01 | LINK LEFT SIDE ASSY OF | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 974 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2205M45G01 | LINK ASSY RIGHT SIDE | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 975 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2205M46G01 | LINK LEFT SIDE | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 976 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2205M47P01 | AXE LINK VERTICAL | 72-64-08 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|----------------------|-------------|-------------|------------------------------|----------|--|
| 977 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2206M23G02 | LINK LEFT SIDE ASSY OF | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 978 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2206M23G03 | LINK LEFT SIDE ASSY OF | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 979 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2206M31G01 | LINK LATERAL MOUNT SIDE | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 980 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2206M31G02 | LINK LATERAL MOUNT SIDE | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 981 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2206M32G01 | LINK AXIAL ASSY OF | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 982 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2206M32G02 | LINK AXIAL ASSY OF | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 983 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2206M53P01 | BUSHING | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 984 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2206M54P01 | AXIS LINK MOUNT TOP AXIAL | 72-64-08 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|-----|------------|----------------|-------------------------------------|-------------|-------------|--------------------------------|----------|--|
| 985 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | J1494P07A | BOLT-MACHINE, DOUBLE HEX HD | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 986 | 11/Jun/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | J644P07A | BOLT-MACHINE, DOUBLE HEX HD | 72-64-08 | Overhaul, Repair, Inspection, Testing |
| 987 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5W2046 | SUPPORT , A/O NO.2 BEARING | 72-32-17 | Overhaul, Repair, Inspection, Testing |
| 988 | 11/Jun/24 | Limited Engine | IAE - EM PN 2A4407 and PN 2A4416 | V2500 | 5W2253 | SUPPORT , A/O NO.2 BEARING | 72-32-17 | Overhaul, Repair, Inspection, Testing |
| 989 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 3066T16G01 | CASE-FAN BLD | 72-23-01 | Overhaul, Repair, Inspection, Testing |
| 990 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 3066T16G02 | CASE-FAN BLD | 72-23-01 | Overhaul, Repair, Inspection, Testing |
| 991 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 3066T16G04 | CASE-FAN BLD | 72-23-01 | Overhaul, Repair, Inspection, Testing |
| 992 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 3066T16G05 | CASE-FAN BLD | 72-23-01 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|------|------------|----------------|----------------------|-------------|---------------|--------------------------|----------|--|
| 993 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 3066T16G06 | CASE-FAN BLD | 72-23-01 | Overhaul, Repair, Inspection, Testing |
| 994 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8C | 3066T16G07 | CASE-FAN BLD | 72-23-01 | Overhaul, Repair, Inspection, Testing |
| 995 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-046-602-0 | HOUSING ASSY,MAIN GBX | 72-63-01 | Overhaul, Repair, Inspection, Testing |
| 996 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-046-603-0 | HOUSING ASSY,MAIN GBX | 72-63-01 | Overhaul, Repair, Inspection, Testing |
| 997 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-046-604-0 | HOUSING ASSY,MAIN GBX | 72-63-01 | Overhaul, Repair, Inspection, Testing |
| 998 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-046-605-0 | HOUSING ASSY,MAIN GBX | 72-63-01 | Overhaul, Repair, Inspection, Testing |
| 999 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1694M17G01 | RETAINER ASSY | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 1000 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1694M17G02 | RETAINER ASSY | 72-41-03 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|------|------------|----------------|----------------------|-------------|-------------|----------------------------|----------|--|
| 1001 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 1694M17G03 | RETAINER ASSY | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 1002 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M36G03 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 1003 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M36G04 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 1004 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M36G05 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 1005 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M36G06 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 1006 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M36G07 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 1007 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M36G08 | VANE-OUTLET GUIDE STG 9 | 72-41-03 | Overhaul, Repair, Inspection, Testing |
| 1008 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8E | 4115T35P01 | RING-AXS-B | 72-64-19 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|------|------------|----------------|----------------------|-------------|-------------|------------------|----------|--|
| 1009 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8E | 4115T35P02 | RING-AXS-B | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 1010 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8E | 4115T36P01 | RING-AXS-D | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 1011 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8E | 4115T36P02 | RING-AXS-D | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 1012 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8E | 4115T37P01 | RING-AXS-G | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 1013 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8E | 4115T37P02 | RING-AXS-F | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 1014 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8E | 4115T38P01 | RING-AXS E | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 1015 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8E | 4115T38P02 | RING-AXS E | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 1016 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8E | 4115T39P01 | RING-AXS-C | 72-64-19 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|------|------------|----------------|----------------------|-------------|---------------|----------------------------|----------|--|
| 1017 | 8/Aug/24 | Limited Engine | GE- EM PN GEK105091 | CF34-8E | 4115T39P02 | RING-AXS-E/G | 72-64-19 | Overhaul, Repair, Inspection, Testing |
| 1018 | 8/Aug/24 | Limited Engine | CIR PN 5315653 | PW1100 | 5373613 | LINER A/O-FAN EXIT CASE | 72-21-03 | Overhaul, Repair, Inspection, Testing |
| 1019 | 8/Aug/24 | Limited Engine | CIR PN 5315653 | PW1100 | 5373614 | LINER A/O-FAN EXIT CASE | 72-21-03 | Overhaul, Repair, Inspection, Testing |
| 1020 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 335-302-902-0 | GEARSHAFT ASSY 73 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1021 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 335-302-906-0 | GEARSHAFT ASSY 73 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1022 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 335-303-002-0 | GEARSHAFT ASSY 41 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1023 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 335-303-201-0 | GEARSHAFT 73-44 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1024 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 335-303-503-0 | GEARSHAFT ASSY 73 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|------|------------|----------------|----------------------|-------------|---------------|-------------------------|----------|---------------------------------------|
| 1025 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 335-303-506-0 | GEARSHAFT ASSY 73 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1026 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 335-303-601-0 | GEARSHAFT ASSY 44 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1027 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 335-324-101-0 | GEARSHAFT 73-44 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1028 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-048-301-0 | GEARSHAFT ASSY 55 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1029 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-051-602-0 | GEARSHAFT 73X44 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1030 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-051-801-0 | GEARSHAFT ASSY 47 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1031 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-051-901-0 | GEARSHAFT ASSY 62 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1032 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-051-903-0 | GEARSHAFT ASSY 62 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|------|------------|----------------|----------------------|-------------|---------------|--------------------------------|----------|--|
| 1033 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-052-802-0 | GEARSHAFT ASSY 73 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1034 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-055-202-0 | GEARSHAFT ASSY 61X31 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1035 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-151-101-0 | GEARSHAFT ASSY 41 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1036 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-151-301-0 | GEARSHAFT ASSY 73 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1037 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-151-501-0 | GEARSHAFT ASSY 44 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1038 | 8/Aug/24 | Limited Engine | CFMI-TP-SM 10 | CFM56-7B | 340-154-301-0 | GEARSHAFT ASSY 61X31 TOOTH | 72-63-03 | Overhaul, Repair, Inspection, Testing |
| 1039 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M14G01 | LINER, ACOUSTIC, AFT, OUTER | 72-24-05 | Overhaul, Repair, Inspection, Testing |
| 1040 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M14G02 | LINER, ACOUSTIC, AFT, OUTER | 72-24-05 | Overhaul, Repair, Inspection, Testing |

Repair Station
 MTU Maintenance Serbia d.o.o
 Četvrta Centralna Radna Street 1
 22330 Nova Pazova, Serbia
 FAA Cert. No. MTUY154E

| Num | Input Date | Rating | OEM - Technical Data | Engine Type | Part Number | Part Description | ATA Code | Maintenance Level |
|------|------------|----------------|----------------------|-------------|-------------|-------------------------|----------|---------------------------------------|
| 1041 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M10G01 | ACOUSTIC LINER FAN DUCT | 72-21-20 | Overhaul, Repair, Inspection, Testing |
| 1042 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M10G02 | ACOUSTIC LINER FAN DUCT | 72-21-20 | Overhaul, Repair, Inspection, Testing |
| 1043 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2007M21G02 | ACOUSTIC LINER FORWARD | 72-24-04 | Overhaul, Repair, Inspection, Testing |
| 1044 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M13G01 | ACOUSTIC LINER FORWARD | 72-24-04 | Overhaul, Repair, Inspection, Testing |
| 1045 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M13G02 | ACOUSTIC LINER FORWARD | 72-24-04 | Overhaul, Repair, Inspection, Testing |
| 1046 | 8/Aug/24 | Limited Engine | GE - EM PN GEK109993 | GE90-100 | 2082M13G03 | ACOUSTIC LINER FORWARD | 72-24-04 | Overhaul, Repair, Inspection, Testing |
| 1047 | 8/Aug/24 | Limited Engine | GE- EM PN GEK112081 | CF34-10E | 2230M12G01 | HOUSING | 72-61-01 | Overhaul, Repair, Inspection, Testing |